

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Co.	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Roelofs 2E	Facility Type: natural gas well API # 300452493000	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. 078415


#### LOCATION OF RELEASE

Unit Letter B	Section 15	Township 29N	Range 08W	Feet from the 810	North/South Line North	Feet from the 1770	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.73031 Longitude 107.66005

#### NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 167 MCF	Volume Recovered: none
Source of Release: water dump valve	Date and Hour of Occurrence: 4/26/2011 - 5/5/2011	Date and Hour of Discovery: 5/6/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Technician found a water dump valve on pent roof separator slightly open causing gas to vent to the pit. Technician adjusted the water dump actuator which closed the stem and corrected the issue.		
Describe Area Affected and Cleanup Action Taken.* Natural Gas dissipated to the atmosphere so no clean action was possible.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Courtney Cochran		Approved by District Supervisor:	
Title: Environmental Challenger		Approval Date: 5/12/11	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com		Conditions of Approval: nJK1122355741	Attached <input type="checkbox"/>
Date: 05/10/2011 Phone: 505-326-9457			

\* Attach Additional Sheets If Necessary