Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO 1004-0135

Expire	s: July 31, 201
Lease Serial No	
NIMICEOTOROT	'Λ

6	If Indian, Allottee or Tribe Name
7	If Unit or CA/Agreement, Name and/or No

	•							
SUBMIT IN TRI	PLICATE - Other instruc	ctions on rev	erse side.		7 If Unit or CA/Agre	ement, Name and/or No		
I Type of Well  ☐ Oil Well ☐ Gas Well ☐ Oth	8 Well Name and No GALLEGOS CANYON UNIT 234							
2 Name of Operator BP AMERICA PRODUCTION		9 API Well No 30-045-11714-00-S2						
			(include area code 6 4081	e)	10 Field and Pool, or Exploratory WEST KUTZ PICTURED CLIFFS			
4 Location of Well (Footage, Sec., 7	, R, M, or Survey Descriptio	n)		T I	11 County or Parish,	and State		
Sec 14 T28N R13W NENE 0790FNL 0790FEL 36.667280 N Lat, 108.181630 W Lon					SAN JUAN COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION				<u> </u>	· · · · · · · · · · · · · · · · · · ·		
N. C. C.	☐ Acidize	Deep	en	□ Producti	on (Start/Resume)	☐ Water Shut-Off		
□ Notice of Intent	Alter Casing	_	ture Treat	☐ Reclama		☐ Well Integrity		
Subsequent Report     ■	Casing Repair	_	Construction	☐ Recompl		Other		
Final Abandonment Notice	Change Plans	_	and Abandon	_	rily Abandon			
20	Convert to Injection	_		□ Water D				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  8/12/11 RU Key 142. Pressure test lubricator 250 psi low; 500 psi high 5 min; good test.  BLM on location.  8/15/11 TIH; set CIBP @1340'. Pressure test to 500 psi; 30 min; zero leakage. Rigulatory agencies agree bond log from 1997 is good for plug reference #1 plug: mix & pmp 101 sxs class G neat 1340'-511'; @15.8 ppg, Yield 1.15 cuff/sk. Cement retainer was stung into & approx 3.2 bbls was pmp'd through the retainer of which about 2.1 bbls ended up in the PC perfs @1385'-1409'; cement pressured up to 300 psi repeatedly so decided to sting out & pmp the rest of batch (13.4 bbls) into the 4 1/2" csg. Less than 1 psi pressure on BH.  8/16/11 Mix & pmp 49 sxs class G neat down 4 1/2" csg; 511'-surface; @15.8 ppg, Yield 1.15 Cut								
14 I hereby certify that the foregoing is	Electronic Submission # For BP AMERICA mmitted to AFMSS for pro	A PRODUCTION	N CO., sent to th	ne Farmington	•			
Name (Printed/Typed) CHERRY		cessing by 31		LATORY ANA	•			
			-					
Signature (Electronic S	Submission)		Date 08/22/2	2011	·			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE .			
Approved By ACCEPT	ED		STEPHEN <sub>Title</sub> PETROLE		ER	Date 08/22/2011		
Conditions of approval, if any, are attaches ertify that the applicant holds legal or equivich would entitle the applicant to conditions.	uitable title to those rights in th	es not warrant or ne subject lease	Office Farming	gton				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ike to any department o	r agency of the United		

## Additional data for EC transaction #115624 that would not fit on the form

## 32. Additional remarks, continued

off wellhead below the BH; cement was tagged @23' inside the surface casing. Top off w/16 sxs class G neat @15.8 ppg; Yield 1.15 cuft/sk. This was pmp'd through the 1" pipe into the 8 5/8" surface pipe filling the surface pipe to surface. Monitored 30 min. - no sign of gas. Installed dry hole marker. RD move off location.