Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUI	REAU OF LAND M	IANAGEMENI	OFD 4 4 9046
SUNDRY	NOTICES AND R	EPORTS ON V	VELLS 14 ZUII
Do not use this	form for proposa	als to drill orate	THINGS FIELD OFFICE
andoned well.	Use Form 3160-	3 (APD) forsəн	sh mionogals

Expires July 31, 2010 5. Lease Scrial No. NMSF-078899A 6. If Indian, Allottee or Tribe Name

FORM APPROVED

OMB No 1004-0137

SUBMIT IN TRIPLICATE Other instructions on page 2.					7 If Unit of CA/Agreement, Name and/or No	
l. Type of Well			, - 9		,	
Oıl Well Gas Well Other					8. Well Name and No. Jazz Com No. 1	
2. Name of Operator D. J. Simmons, Inc.					9 API Weli No. 30-045-32116	
3a Address		3b. Phone No.	. (înclude area co	ode)	10 Field and Pool or E	Exploratory Area
1009 Ridgeway Place, Suite 200 Farmington, NM 87401		(505) 326-37	(505) 326-3753		Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T,R.,M., or Survey Description)			,		11. Country or Parish, State	
Surface 1055' FNL & 1545' FWL, Section 21, T-26-N, R-11-W, NMPM				, 	San Juan County, New Mexico	
12. CHECI	K THE APPROPRIATE I	BOX(ES) TO IND	DICATE NATUR	E OF NOTIO	CE, REPORT OR OTHI	ER DATA
TYPE OF SUBMISSION			TY	PE OF ACT	ION	į
▼ Notice of Intent	Acidize	Deep	en	Prod	uction (Start/Resume)	Water Shut-Off
Notice of Intell	Alter Casing	Fract	ture Treat	Recl	amation	Well Integrity
Subsequent Report	Casing Repair'	New	Construction	Reco	mplete	Other
Suosequent Report	Change Plans	· V Plug	and Abandon	Tem	orarily Abandon	
Final Abandonment Notice	Convert to Injectio	n Plug	Back	☐ Wate	r Disposal	
· Kill well as necessary with viscous	nit fluid					E111819202122
-						
Other sundries of intent to plug and	abandon will be filed or				ve plan for execution i	in the next 180 days to allow time
Other sundries of intent to plug and a for preparation and scheduling of ad	abandon will be filed or Iditional wells.	n additional wells			ve plan for execution i	
following completion of the involve testing has been completed. Final Adetermined that the site is ready for  Move in and Rig Up well service ur Kill well as necessary with viscous Trip out of hole and lay down rods, Remove wellhead Secure well with 4 ½" X 2" swage at Move rig out Rig up cementing company to well o Mix 30sx lead cement with 2%CaCo Do not displace cement Wash up equipment to water tank Wait overnight If cement is not at surface, tag and Dig out, cut off, install marker, removed.	abandon will be filed or Iditional wells.	n additional wells			ve plan for execution i	in the next 180 days to allow time
Other sundries of intent to plug and for preparation and scheduling of ad	abandon will be filed or Iditional wells.	n additional wells		ove the abov	ve plan for execution i	in the next 180 days to allow time
Other sundries of intent to plug and a for preparation and scheduling of ad  14. Thereby certify that the foregoing is to Chris S. Lopez	abandon will be filed or Iditional wells.	n additional wells	s. Please appro	ove the above	ve plan for execution i	in the next 180 days to allow time
Other sundries of intent to plug and for preparation and scheduling of ad  14. Thereby certify that the foregoing is to Chris S. Lopez	abandon will be filed or iditional wells.  True and correct. Name (Pri	n additional wells	Title Regula	tory Specia	ve plan for execution i	in the next 180 days to allow time
Other sundries of intent to plug and for preparation and scheduling of ad  14. Thereby certify that the foregoing is tr  Chris S. Lopez  Signature	abandon will be filed or iditional wells.  True and correct. Name (Pri	n additional wells inted/Typed) SE FOR FEDI	Title Regula	tory Specia	ve plan for execution i	in the next 180 days to allow time

fictitious or fraudulent statements or representations as to any matter within its jurisdiction