

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

SEP 14 2011

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1 Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2 Name of Operator
D J Simmons, Inc

3a Address
1009 Ridgeway Place, Suite 200
Farmington, NM 87401

3b Phone No (include area code)
(505) 326-3753

4 Location of Well (Footage, Sec, T, R, M, or Survey Description)

Surface 2595' FNL & 1951' FWL, Section 3, T-26-N, R-12-W, NMPM

5 Log Serial No
NM24080384-B

6 If Indian, Allottee or Tribe Name

7 If Unit of CA/Agreement, Name and/or No

8 Well Name and No
Hiccup A No 3

9 API Well No
30-045-31844

10 Field and Pool or Exploratory Area
Basin Fruitland Coal

11 Country or Parish, State
San Juan County, New Mexico

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water Shut-Off
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity
☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Other
☐ Change Plans ☒ Plug and Abandon ☐ Temporarily Abandon
☐ Convert to Injection ☐ Plug Back ☐ Water Disposal

13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

- Move in and Rig Up well service unit
- Kill well as necessary with viscous fluid
- Trip out of hole and lay down rods, pump and production tubing
- Remove wellhead
- Secure well with 4 1/2" X 2" swage and ball valve
- Move rig out
- Rig up cementing company to well
- o Mix 30sx lead cement with 2%CaCl2, 1/4#/sx cellophane, 3#/sx gilsonite to 15 6 ppg followed by 70sx cement with 2%CaCl2 at 4bpm
- o Do not displace cement
- o Wash up equipment to water tank with 25# sugar added
- Wait overnight
- If cement is not at surface, tag and top with neat cement as necessary
- Dig out, cut off, install marker, remediate location as indicated in conditions of approval

Other sundries of intent to plug and abandon will be filed on additional wells. Please approve the above plan for execution in the next 180 days to allow time for preparation and scheduling of additional wells.

RCVD SEP 19 '11
OIL CONS. DIV.
DIST. 3

SV 9-14-11

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Chris S Lopez

Title Regulatory Specialist

Signature

Chris S. Lopez

Date 09/14/2011

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

SEP 16 2011

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD