District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003 Submit 2 Copies to appropriate

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
30-045-33171						OPERATOR Initial Report Final Report						
Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company						Contact Shelly Cook-Cowden						
Address 3401 E. 30 th St., Farmington, NM 87402						Telephone No. 505-324-5140						
Facility Name San Juan 32-9 Unit #241S						Facility Type Gas Well						
Surface Owner Federal Mineral Owner						Federal [Lease No. NMSF - 079329		
LOCATION OF RELEASE												
Unit Letter D	Section 13	Township 32N	Range 09W	Feet from the 705'		/South Line North	Feet from the 705'	East/West Line West		County San Juan		
Latitude 36.98966 ° N Longitude -107.73707 ° W												
NATURE OF RELEASE												
Type of Rele							e Recovered - 0					
Source of Release – level controller failure on dump									@8:45A	d Hour of Discovery – 10/12/11 AM		
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required						If YES, To Whom? Brandon Powell NMOCD- Via voicemail & follow-up email Mark Kelly – BLM via phone conversation & follow-up email						
By Whom? Shelly Cook-Cowden						Date and Hour – 10/18/11 @ 1:27PM						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercon	urse was Im	pacted, Descr	ibe Fully.	*						/ 60	RECLIVED OCT 2011 OLL CONS. DIV. DIST. 3	
Describe Cause of Problem and Remedial Action Taken.* The dump on the suction scrubber hung open due to a malfunction of the level controller which would not allow the dump to close 110168195.												
Describe Area Affected and Cleanup Action Taken.* None. The release was to atmosphere and there was no fluid associated with the gas release. The level controller has been replaced and tested. No further action is required.												
regulations a public health should their or the enviro	Il operators or the envi operations I nment. In a	are required to ronment. The nave failed to	o report as acceptanadequately OCD accep	e is true and completed ind/or file certain rece of a C-141 report investigate and rectance of a C-141 records.	lease r rt by the median	notifications a ne NMOCD m te contaminat	nd perform correct parked as "Final R ion that pose a thing the operator of	ctive ac Report" reat to g	tions for rel does not rel ground wate sibility for c	eases which ieve the ope r, surface w ompliance	n may endanger erator of liability rater, human health with any other	
						OIL CONSERVATION DIVISION						
Signature:	Sheller		Approved by District Supervisor: Syundon Travell									
Printed Nam	e: Shelly C	- 1										
Title: Field Environmental Specialist						Approval Date: 10/26/11			Expiration Date:			
E-mail Address: Shelly.g.Cook-Cowden@ConocoPhillips.com						Conditions of Approval:				Attached		
Date: Octobe	er 20, 2011		Pl	hone: 505-324-514								

nJK1129954190