

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-045-11475

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	<b>Burlington Resources, A Wholly Owned Subsidiary of ConocoPhillips Company</b>	Contact	<b>Kelsi Harrington</b>
Address	<b>3401 E. 30<sup>th</sup> St., Farmington, NM 87402</b>	Telephone No.	<b>505-599-3403</b>
Facility Name	<b>Ute 1 SWD</b>	Facility Type	<b>Gas Well API# 3004511475</b>
Surface Owner	<b>Ute Mountain Ute</b>	Mineral Owner	<b>Ute Mountain Ute</b>
		Lease No.	<b>I-22-IND-2772</b>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>M</b>	<b>11</b>	<b>32N</b>	<b>14W</b>	<b>560'</b>	<b>South</b>	<b>315'</b>	<b>West</b>	<b>San Juan</b>

Latitude **36.99709° N** Longitude **-108.28589° W**

**NATURE OF RELEASE**

Type of Release – <b>Produced Water</b>	Volume of Release – <b>5 BBL</b>	Volume Recovered – <b>0 BBL</b>
Source of Release: <b>Discharge Line</b>	Date and Hour of Occurrence <b>unknown</b>	Date and Hour of Discovery <b>12/16/2010 11:30 AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour –	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\* **A release from a SWD discharge line at the Ute #1 SWD transporting produced water was discovered on 12/16/10. Upon discovery, the discharge line was shut in. The leak was caused by corrosion to the pipe.**

Describe Area Affected and Cleanup Action Taken.\* **All fluid remained on location and no fluid was recovered. The release occurred in the area of an excavation for a previous release therefore confirmation sampling occurred after excavation was completed. Analytical results were below the regulatory standards set forth in the NMOCD Guidelines for Remediation of Leaks, Spills and Releases; therefore no further action is needed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Harrington</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kelsi Harrington</b>	Approved by District Supervisor: <i>Jonathan D. Kelly</i>	
Title: <b>Environmental Consultant</b>	Approval Date: <b>12/08/2011</b>	Expiration Date:
E-mail Address: <b>kelsi.g.harrington@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>1/7/10</b>	Phone: <b>505-599-3403</b>	

\* Attach Additional Sheets If Necessary



nJK1134242182