

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Co.	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington NM 87401	Telephone No.: 505-326-9457	
Facility Name: Atlantic B LS 2C	Facility Type: natural gas well API # 300453217100	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. NMSF 080917

LOCATION OF RELEASE

Unit Letter G	Section 04	Township 30N	Range 10W	Feet from the 1800	North/South Line North	Feet from the 1590	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.84296 Longitude 107.88457

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 1370 MCF	Volume Recovered: none
Source of Release: rupture disk	Date and Hour of Occurrence: 2/23/2011 - 4/11/2011	Date and Hour of Discovery: 5/5/2011
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD Sherrie Landon - BLM	
By Whom? Courtney Cochran	Date and Hour: 5/5/2011 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RCVD MAY 10 '11
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

1/2" rupture disk relieved on the fuel gas system. Rupture disk functioned as designed. It is believed that another valve may have failed causing the rupture disk to blow. RCFA is being conducted. Well is currently shut-in.

Describe Area Affected and Cleanup Action Taken.*

Natural Gas dissipated into the atmosphere so no clean-up action was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor: 	
Title: Environmental Challenger	Approval Date: 12/28/2011	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/09/2011	Phone: 505-326-9457	

* Attach Additional Sheets If Necessary

nJK1136256068