

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-31259

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Courtney Cochran
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9457
Facility Name: Gartner A3M	Facility Type: natural gas well API # 300453125900

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 080597
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter E	Section 33	Township T30N	Range R8W	Feet from the 2290	North/South Line North	Feet from the 770	East/West Line West	County: San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------------

Latitude 36.79121 Longitude 107.7093

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 679 MCF of gas	Volume Recovered: no gas recovered
Source of Release: rupture disk on fuel pot separator	Date and Hour of Occurrence: 1:00 pm on 12/7 until 11:00 am on 12/12	Date and Hour of Discovery: 12/12/2011
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell NMOCD	
By Whom? Courtney Cochran	Date and Hour: 1:00 pm on 12/13/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RCVD DEC 22 '11
OIL CONS. DIV.

Describe Cause of Problem and Remedial Action Taken.*



Rupture disk blew on the HLP separator fuel pot. Well is shut-in and a RCFA will be conducted.

DIST. 3

Describe Area Affected and Cleanup Action Taken.*

The gas released dissipated into the atmosphere so no clean-up action was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor: 	
Title: Environmental Challenger	Approval Date: 1/10/2012	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 14, 2011 Phone: 326-9457		

* Attach Additional Sheets If Necessary

nJK 1201046660