Form 3 160-5 (August 1999)

Name (Printed/Typed)

Signature

Paul C. Thompson, P.E.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVE

FORM APPROVED OMB No 1004-0135 Expires Jnovember 30, 2000

Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS

MAR 19 2012

SF 081100-A

Do not use this form for proposals to drill or reenter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposassinington Field Office Bureau of Land Managemen. 7. If Unit or CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on reverse side Type of Well Oil Well **X** Gas Well Other 8. Well Name and No Name of Operator Ram #1 Running Horse Production Co. 9 API Well No. Address 30-045-21942 Phone No (include area code) P.O. Box 369, Ignacio, CO 81137 505-327-4892 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Gallegos Fruitland Sand - PC 890' FNL & 790' FEL. Section 8. T26N. R12W 11 County or Parish, State San Juan County, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Alter Casing Fracture Treat Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once. Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the star is ready for facilities the interval of the proposal control of the involved operator. determined that the site is ready for final inspection.) Running Horse Production Co. plans to plug and abandon the Ram #1 according to the attached procedure. E'ISIO OIF COM2' DIM' BCAD WAR 29'I'Z I hereby certify that the foregoing is true and correct

Title Approved by Date MAR 2 3 2012 Original Signed: Stephen Mason Conditions of approval, if any, are attached. Approval of this notice does not warrant or Office certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

THIS SPACE FOR FEDERAL OR STATE USE

Title

Date

Agent / Engineer

March 15, 2012

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Walsh Engineering and Production

P & A Procedure for Running Horse Production Co. Ram #1

Location: NE/4 Sec 8 T26N R12W Date: March 15, 2012

San Juan County, NM

Field: Gallegos Fruitland Sand - PC Elev: GL 5967' Surface: BLM 4-1/2" @ 1189'

Minerals: BLM SF 081100-A PBTD 990' GL

Procedure:

1. MOL and RU completion rig. Hold safety meeting.

- 2. NU 2-3/8" relief line. Blow well down and kill with water if necessary.
- 3. TOH and lay down approximately 28 joints (902') of 1-1/4" tubing.
- 4. Remove the 4-1/2" tubing head.
- 5. Connect cement truck directly to 4-1/2" casing. Establish an injection rate with water then fill the casing with 80 sx (94.4 cu.ft.) of Type 5 cement with 3% CaCl₂. Pump cement until the casing stands full.
- 6. Cut off wellhead and install dryhole marker. Reclaim location as per BLM specifications.

Paul C. Thompson, P.E.

STATE OFFICE STATE OFFICE

M.-MAILROOM

SITATE OFFICE SANTA FE, NEW ME) **2012 HAR 28** 2011EEZED W/40 SK HO , 7611 - 68/1 CMT W/ 1205K ,6811 D#2.P,34 PICTURES CLIFFS . 066- 37+ XI DOL tas 2 029 1/9- 310H 80 54(94.400.4) 一半かっと 1206の221次 1018- DNASTING 15 8 M 1m) 070 # 87 1L · Surate Abq CUZZENT STATUS 30-042-51945

.L965-1373

FRANIMA HORSE PRODUCTION GO
FAM #1
890 FNL & 790 FEL SEC. 8, TELN, RIEW

× · · · ·

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON FIELD OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of

Re: Permanent Abandonment

Intention to Abandon:

Well: 1 Ram

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) After plug has set, tag top of cement and refill casing with cement if necessary.
- b) Since the top of cement behind the 2 7/8" casing is unknown, a cement plug between the 7" and the 4 $\frac{1}{2}$ "" casings may be necessary.

Office Hours: 7:45 a.m. to 4:30 p.m.

B.L.M.-MAILROOM

2012 MAR 28. PH 2: 34

STATE OFFICE