

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-30449

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Shelly Cook-Cowden	
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-324-5140	
Facility Name San Juan 27-4 Unit 109M	Facility Type Gas Well API 3003930449	
Surface Owner Federal	Mineral Owner Federal	Lease No. SF - 080672

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	24	32N	07W	1680'	SOUTH	1750'	WEST	San Juan County

Latitude - 36.96310 ° N Longitude - 107.520817 ° W

RCVD MAR 21 '12
OIL CONS. DIV.
DIST 3

NATURE OF RELEASE

Type of Release - Gas	Volume of Release - 246 MCF	Volume Recovered - 0
Source of Release - inlet pressure control valve & Rupture Disk	Date and Hour of Occurrence - 1/7/12 @ 4:25PM	Date and Hour of Discovery - 1/8/12 @ 8:25 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour -	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken ***Inlet pressure control valve on separator was washed out by sand causing the separator to over pressure and the PRV to start venting. As the pressure increased the rupture disk on the separator vented causing the separator to vent freely.**

Describe Area Affected and Cleanup Action Taken. ***The well was shut-in and the inlet pressure control valve was repaired; therefore no further action is required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shelly Cook-Cowden</i>		OIL CONSERVATION DIVISION	
Printed Name: Shelly Cook-Cowden		Approved by District Supervisor: <i>Jonathan Kelly</i>	
Title: Field Environmental Specialist		Approval Date <i>3/21/2012</i> Expiration Date: <i>3/21/2013</i>	
E-mail Address: Shelly.g.Cook-Cowden@ConocoPhillips.com		Conditions of Approval:	
Date: January 13, 2012 Phone: 505-324-5140		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

NJK 1208154881