

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-30606 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company <u>ENERGY RESOURCES</u>	Contact <u>KELLIE CAMPBELL</u>
Address <u>2010 APTON PLACE</u>	Telephone No. <u>505-793-7611</u>
Facility Name <u>CARRACAS #18 B3</u>	Facility Type <u>ON SHORE WELL</u>

Surface Owner <u>FEDERAL</u>	Mineral Owner <u>FEDERAL</u>	Lease No <u>39-30606</u>
------------------------------	------------------------------	--------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	18	32N	4W					

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>FIRE</u>	Volume of Release <u>0</u>	Volume Recovered <u>0</u>
Source of Release <u>FRICTION + GAS KICK</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>10/12/2010 1500</u> <u>KELLIE CAMPBELL / BRANDON POWELL</u>	<u>10/12/2010 1500</u> <u>2:00p</u>
By Whom? <u>KELLIE CAMPBELL</u>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <u>N/A</u>	<u>RCVD OCT 14 '10</u> <u>OIL CONS. DIV.</u> <u>DIST. 3</u>
If a Watercourse was Impacted, Describe Fully * <u>N/A</u>		
Describe Cause of Problem and Remedial Action Taken * <u>SLICK ROD WAS RUNNING CO-ROD INTO WELL. DUE TO A MIS-ALIGNMENT AT INJECTOR HEAD PARTS GOT HOT. THE WELL TOOK A KICK CAUSING A FIRE AT THE CO-ROD & INJECTOR HEAD</u>		
Describe Area Affected and Cleanup Action Taken * <u>CREW IMMEDIATELY CLOSED BOPS & EXTINGUISHED FIRE WITH FIRE EXTINGUISHERS. SLICK ROD UNIT WAS REMOVED FROM SERVICE & REPAIRED SO THAT IT DO NOT CREATE FRICTION DURING OPERATION.</u>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature <u>Kellie Campbell</u>	OIL CONSERVATION DIVISION	
Printed Name <u>Kellie Campbell</u>	Approved by District Supervisor <u>[Signature]</u>	
Title <u>ENV / SAFETY COOR</u>	Approval Date <u>3/6/2012</u> Expiration Date	
E-mail Address <u>kellie.campbell@energy.com</u>	Conditions of Approval	Attached <input type="checkbox"/>
Date <u>10/18/2010</u> Phone <u>505-793-7611</u>		

* Attach Additional Sheets If Necessary

nJK1206640495