District I 1625 N French Dr , Hobbs, NM 88240 1301 W Grand Avenue, Artesia, NM88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action


Submit 2 Copies to appropriate District Office in accordance

with Rule 116 on back side of form


Form C-141

Revised October 10, 2003

40-043-20110						OPERATO	☐ Initial Report ☐ Final Report					
Name of Company: Energen Resources, Inc.							Ed Hasely					
Address: 2010 Afton Place, Farmington, NM 87401						Telephone No: 505-324-4131						
Facility Name: Jicarilla 183 #6, API No 3004520110 Facility Type: Oil/Gas Well Site												
Surface Owner: Jicarilla Mineral Owne						Jicarılla	Lease No. Jicarilla 183					
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
· · · · · · · · · · · · · · · · · · ·				No: Sou	rth/South Line uth	East/West Line County East Rio Arriba			a			
			Latit	ude_36 19015	Longitud	e <u>-107 14008</u>						
NATURE OF RELEASE												
Type of Rele	ase: Compres	ssor Engine Fi	re			Volume of Release: Volu <5 MCF – Natural Gas			me Recovered: 0			
Source of Re	lease: Compi	essor Engine				Date and Hour 3/8/12	of Occurrence:	Occurrence: Date and Hour of Discovery: 3/8/12, 9 30 am				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required ☐ Not Requ												
By Whom? Kellie Campbell / Billy Stalcup						Date and Hour: 3/8/12 4 00 pm – OCD, 3/9/12 11 50 am – Jicarilla BLM						
Was a Water	course Reac		Yes 🛛	No	If YES, Volume Impacting the Watercourse. NA							
If a Watercourse was Impacted, Describe Fully.* NA RCVD MAR 14'12 OIL CONS. DIV. DIST. 3 Describe Cause of Problem and Remedial Action Taken.* A small compressor fire was discovered on the subject location on 3/8/12 Investigations point to the possibility that an oil leak sprayed onto the exhaust manifold causing the fire. The gas supply was shut off and the fire went out												
Describe Area Affected and Cleanup Action Taken.* Fire was confined to the compressor unit												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of hiability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature DHasel						OIL CONSERVATION DIVISION						
						Approved by District Supervisor						
						Approval Date 3/21/2012 Expiration Date						
E-mail Addre	ess <u>ed.hasely</u>	@energen.cor	<u>n</u>		-	Conditions of App	roval		Attached			
Date 3/13/12				505-330-3584(cell			<u> </u>					
* Attach Addı	tional Sheet	s If Necessar	У			1	JK12081	55149				



DIST. 3



New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410 Attn: Brandon Powell

Jicarilla 183 #6 Re:

Fire/Release Report Submittal

Dear Mr. Powell:

Enclosed is the final Release Notification and Corrective Action (C-141) Form for the recently discovered fire on the subject well location.

If there are any questions or concerns with this submittal, please contact me at 505-324-4131.

Sincerely,

Ed Hasely

Sr. Environmental Engineer

Energen Resources

Attachment: Final C-141

Cc: Bryce Hammond – BLM/Jicarilla

> **HSE File** Facility File Correspondence