

Submit 3 Copies to Appropriate District Offices	State of New Mexico Energy, Minerals and Natural Resources	Department	Form C-103 Revised 1-1-89
DISTRICT I	OIL CONSERVATION DIX	JISION	
P.O. Box 1980, Hobbs, NM 88240	P.O. BOX 2088		0.
DISTRICT II	Santa Fe, New Mexico 87504-2		0-045-07792
P.O. Drawer DD, Artesia, NM 88210	No.	7263	pe of Lease
DISTRICT III	The second secon	2005	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410		State Oil &	à Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FO	R PROPOSALS TO DRILL OR TO DETERM OR PLUG	BACK TO A 7. Lease Nan	ne or Unit Agreement Name
DIFFERENT F	RESERVOIR. USE "APPLICATION FOR PERMIT"	2 1 5 1 C 1 C 2 C 2 C 2 C 2 C 2 C 2 C 2 C 2 C	
	DRM C-101) FOR SUCH PROPOSALS.)	a Laber	C W
1. Type of Well:			Sullivan
1 1	GAS X OTHER		
2. Name of Operator	WELL	8. Well No.	
El Pamco, Inc.			5
3. Address of Operator		9. Pool name	or Wildcat
P. O. Box 14738 Albuquerque, NM 87191-4738			ec Pictured Cliffs / Aztec Fruitland
4. Well Location			
Unit LetterA	: 1145' Feet From The East	Line and1030'	Feet From The North Line
30	20N	5 10W/ 15 mm	Con Ivon
Section 30	Township 29N 10. Elevation (Show wheth	Range 10W NMPI	M San Juan County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5494' GR			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
NOTICE OF I	MIENTION TO.	SUBSEQU.	ENT KEPOKT OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JO	в
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
El Pamco. Inc. proposes to plug and abandon the subject well as follows:			
El Pamco, Inc. proposes to plug and abandon the subject well as follows:			
1. Set CIBP at 1422' and cap with 100' plug (12 sx) from 1322' to 1422'.			
2. Shoot 4 JSPF at 750'.			
3. Circulate cement outside and inside of casing from 0' to 750' (300 sx)			
4. Cut of	ff wellhead and erect dry hole n	narker.	,
•			
i .			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Dava	J Delice that THE	Agent	DATE
TYPE OR PRINT NAME Dana L. Delventhal TELEPHONE NO. (505) 326-4125			
(This space for State Use) DEPUTY OIL 8 GAS INSPECTOR, DIST. SEMAR 1 8 2005			
APPROVED BY Charle APPROVED BY Charles APPROVE			

CONDITIONS OF APPROVAL, IF ANY:

Sullivan No. 5 (Current)





Sullivan No. 5 (Proposed)

1145' FEL, 1030' FNL Sec. 30, T29N, R10W

