

District I
1625 N French Dr., Hobbs, NM 88240
District II
811 S First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

30-039-30044

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Ashley Maxwell
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-324-5169
Facility Name San Juan 28-5 Unit 89F	Facility Type Gas Well Lease # NMSF-079250

Surface Owner Federal	Mineral Owner Federal	API No. 3003930044
------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	10	028N	005W	1600'	South	940'	West	Rio Arriba

Latitude **36.67288** Longitude **-107.35182**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 19 BBL	Volume Recovered 19 BBL
Source of Release Production Pit	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 2/12/12 @ 2:05 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD MAY 17 '12	
By Whom?	Date and Hour OIL CONSERV DIV	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The production pit overflowed. The fluid remained within the cribbing and was removed with a water truck. 19 BBL were recovered.

Describe Area Affected and Cleanup Action Taken.*

All the fluid remained within the cribbing. 19 BBL was recovered. ConocoPhillips Company will assess the soils to determine further action, if needed. **The soil within the cribbing has NO staining and/or crusting; therefore, no further action is required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ashley Maxwell	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 5/25/2012	Expiration Date:
E-mail Address: ashley.p.wethington@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 15, 2012 Phone: 505-324-5169		

* Attach Additional Sheets If Necessary

NJK 1214628531