


District I - (505) 393-6161
P O Box 1980
Hobbs, NM 88241-1980

District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131



Form C - 141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name Phillips Petroleum Company	Contact Robert A. Wirtanen
Address 5525 Hwy. 64, Farmington, New Mexico 87401	Telephone Number (505) 599-3462
Facility Name San Juan 32-7 Unit: Well #241	Facility Type Gas Well

Surface Owner Jack Macky	Mineral Owner FEE	Lease No API # 30-045-29546
------------------------------------	-----------------------------	---------------------------------------

51 CR 4012 Ignacio, CO 81137

LOCATION OF RELEASE

Unit Letter G	Section 21	Township 32N	Range 7W	Feet from the 2234'	North/South Line North	Feet from the 1841'	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	--------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

NATURE OF RELEASE

Type of Release	Volume of Release est. 80 BBLs	Volume Recovered 80 BBLs
Source of Release Broken Weld connection on 2" buried plastic piping system	Date & Hour of Occurrence 2/2/00	Date & Hour of Discovery 1500 02/02/2000
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - by tele-fax NMOCD by tele-fax	
By Whom? Robert A. Wirtanen	Date and Hour 2/3/00 1530 hr	
Was a Watercourse Reached? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO water did not leave the tank berm	If YES, Volume Impacting the Watercourse no spilled water impacted a watercourse	
If a Watercourse was impacted, describe fully (Attach additional sheets if necessary) na		

Describe cause of problem and remedial action taken (attach additional sheets if necessary)

Water was discovered inside the cathern berm around the tank storage. Weld had broken and leaked water. No water left the diked area around tank nor the lease.

Describe area affected and cleanup action taken (Attach additional sheets if necessary)

80 BBLs spilled and 100% recovered and pumped back into storage tank Plastic piping system repaired 2/3/00

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the Operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature original signed by R A Wirtanen & faxed 02/03/2000 <i>RAW</i>	OIL CONSERVATION DIVISION	
Printed Name Robert A Wirtanen	Approved by <i>Dennis L. Jant</i> District Supervisor	<i>for Frank Chavez</i>
Title Sr. Safety & Environmental Specialist	Approval Date 2/9/2000	Expiration Date
Date 2/3/00	Phone (505) 599-3462	Conditions of Approval Attached <input type="checkbox"/>