

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

## State of New Mexico

## Energy Minerals and Natural Resources Department

## Oil Conservation Division

2040 South Pacheco Street  
Santa Fe, New Mexico 87505  
(505) 827-7131

Form C-141  
Originated 2/13/97

Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report☐ Final Report

Name:	Burlington Resources	Contact:	Ed Hasely
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9537
Facility Name:	COZZENS 6	Facility Type:	Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-077056
----------------	---------	----------------	---------	---------------	-------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
L	18	029N	011W	1850	South	790	West	

## NATURE OF RELEASE

Type of Release:	Condensate	Volume of Release:	50 bbls.	Volume Recovered:	0 bbls.
Source of Release:	Condensate Tank	Date and Hour of Occurrence:	6/16/00	Date and Hour of Discovery:	6/16/00 1:30:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom? Denny Foust			
By Whom?	Ed Hasely	Date and Hour: 6/16/00 3:00:00 PM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0			

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

The gasket around the manway on the condensate tank broke allowing the condensate to leak out of the tank. No fluid escaped the bermed area. No fluids were recovered.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All fluids were contained inside the bermed area. The soils have been excavated and landfarmed on location and on the adjacent Cozzens #1R location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Ed Hasely</i>	OIL CONSERVATION DIVISION	
Printed Name:	Ed Hasely	Approved by:	<i>Denny Foust</i>
Title: Environmental Representative		District Supervisor:	<i>For Frank Chavez</i>
Date:		Approval Date:	<i>7/10/00</i>
Phone: (505) 326-9537 or (505) 326-9841		Expiration Date:	
Conditions of Approval:		Attached: <input type="checkbox"/>	

Remaining contamination  
with WFS  
DGF00168551


# BURLINGTON RESOURCES

---

SAN JUAN DIVISION

June 27, 2000

New Mexico Oil Conservation Division  
C/O Denny Foust  
1000 Rio Brazos Road  
Aztec, NM 87410



**Re: Report of an Undesirable Event**  
**Cozzens #6 Initial Report**

Dear Mr. Foust:

The purpose of this correspondence is to provide you with two copies of the "Initial Report" for the undesirable event that occurred June 16, 2000, at the Cozzens #6 located in Unit L, Section 18, Township 29N, Range 11W.

As per your most recent visit to the location on June 26, 2000 soils have been excavated and a potential second source of soil contamination was identified. BR is currently determining the owner of a pit on location to assess the next step in remediation.

If you have any questions or need additional information, please contact me at 326-9841.

Sincerely,

A handwritten signature in black ink, appearing to read "Ed Hasely".

Ed Hasely  
Environmental Representative

Attachments: Release Notification Form

cc: Mark Kelly - BLM  
Steve Florez  
Shanna Nava  
Correspondence