

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131


State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97



Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

30-045-28942

OPERATOR

☐ Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Gregg Wurtz
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9537
Facility Name:	SAN JUAN 32-9 UNIT	18R	Facility Type: Gas Well

Surface Owner:	BLM	Mineral Owner:	BLM	Lease Number:	NMSF-078386
----------------	-----	----------------	-----	---------------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
K	17	031N	009W	1615	South	1780	west	

NATURE OF RELEASE

Type of Release:	Condensate	Volume of Release:	35 bbls.	Volume Recovered:	32 bbls.
Source of Release:	Condensate tank overflow	Date and Hour of Occurrence:	2/22/00 7:00:00 AM	Date and Hour of Discovery:	2/23/00 6 00:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom? Denny Foust, OCD Aztec, NM			
By Whom?	Gregg Wurtz	Date and Hour: 2/24/00 2:30:00 PM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0			

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

No watercourse or surface water body was impacted

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Historical well condensate production significantly increased for unknown reasons causing storage tank to overflow into secondary containment prior to scheduled routine tank pumping. Released condensate was removed immediately after discovery. Soils were removed within 12 hours of discovery. Tank and pit tank moved and an estimated 10 cu. yds. of material was excavated from within the bermed area and landfarmed on site.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All condensate contained within tank secondary containment. Contaminated soil excavated vertically and horizontally to the extent of no visible contamination.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name:	Gregg Wurtz	Approved by:	<i>Denny Foust</i>
Title: Environmental Representative		District Supervisor:	<i>for Frank Chavez</i>
Date:	Phone: (505) 326-9537 or (505) 326-9841	Approval Date:	<i>3/22/00</i>
		Expiration Date:	
		Conditions of Approval:	Attached: <input type="checkbox"/>

n 56F 0000035