

P O Box 1980  
Hobbs, NM 88241-1980  
District II - (505) 748-1283  
811 South First  
Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Road  
Aztec, NM 87410  
District IV - (505) 827-7131


Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street  
Santa Fe, New Mexico 87505  
(505) 827-7131

Form 1-141  
Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form



Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name <i>Cross Timbers Operating Company</i>	Contact <i>John Rector</i>	
Address <i>6001 HY 64 FARMINGTON, NM 87401</i>	Telephone No. <i>505-632-5200</i>	
Facility Name <i>DAVINSON Gas Com G#1</i>	Facility Type <i>Oil &amp; Gas Well location</i>	
Surface Owner <i>BLM</i>	Mineral Owner <i>Fed</i>	Lease No <i>14080016744</i>

LOCATION OF RELEASE

Unit Letter <i>H</i>	Section <i>21</i>	Township <i>28N</i>	Range <i>10W</i>	Feet from the <i>1850</i>	North/South Line <i>N</i>	Feet from the <i>790</i>	East/West Line <i>E</i>	County <i>SAN JUAN</i>
-------------------------	----------------------	------------------------	---------------------	------------------------------	------------------------------	-----------------------------	----------------------------	---------------------------

NATURE OF RELEASE

Type of Release <i>oil leak</i>	Volume of Release <i>20</i>	Volume Recovered <i>0</i>
Source of Release <i>Bullet hole in PROD. oil tank</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Denny Foust</i>	
By Whom? <i>John Rector</i>	Date and Hour <i>8/18/00 5:00 p.m.</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

*VANDALS shot 3 holes in prod. tank. Notified SAN JUAN county Sheriff & BLM Law Enforcement.*

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

*Contaminated soil was dug and left on location. New soil was brought into fill hole.*


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>John C Rector</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>John Rector</i>	Approved by <i>Denny Foust</i>	District Supervisor <i>for Frank Chavez</i>
Title: <i>PRODUCTION FOREMAN</i>	Approval Date: <i>8/30/00</i>	Expiration Date:
Date: <i>8/28/00</i>	Phone: <i>632-5200</i>	Conditions of Approval:
		Attached <input type="checkbox"/>

#N06F002342784 Remediation Report attached 2

# FIGURE 1

SCHEMATIC  
NOT TO  
SCALE



TO WELL  
HEAD

AUG 23, 2000

SAMP PT ID	OVM READING (ppm)
1 @ 15 FT.	00
2 @ 15 FT.	176
3 @ 15 FT.	00
4 @ 15 FT.	346
5 @ 15 FT.	1,096

STATE REGULATIONS	OVM 100 ppm
-------------------	-------------

NOTES  
EXCAVATION DEPTH @ APPROX 15 FT. BELOW GRADE (SANDSTONE BEDROCK ENCOUNTERED). SOIL MOSTLY MOD YELL. BROWN SAND WITH BLACK DISCOLORATION OBSERVED @ BEDROCK SURFACE (USUALLY INDICATING OLD/BIODEGRADED CONTAMINATED SOIL) DISCOLORED SOIL COLLECTED BELOW BURIED LOAD LINE @ SAMPLE POINT (2). ALL SAMPLES COLLECTED FROM BEDROCK, THEREFORE NO TPH ANALYSIS WAS CONDUCTED

OVM = ORGANIC VAPOR METER (FIELD INSTRUMENT)

TANK CENTER IS @ APPROX 154 FT. N51E FROM WELL HEAD

APPROX 23 CUBIC YARDS REMOVED & STOCKPILED ON-SITE

CROSS TIMBERS OIL COMPANY

DAVIDSON GC G #1

SE/4 NE/4 SEC 21, T28N. R10W

SAN JUAN COUNTY, NEW MEXICO

BLAGG ENGINEERING, INC.

CONSULTING PETROLEUM / RECLAMATION SERVICES

P.O. BOX 87

BLOOMFIELD, NEW MEXICO 87413

PHONE (505) 632-1199

PROJECT: SPILL CLEANUP

DRAWN BY: NJV

FILENAME: DAVID-G1.SKD

SITE  
MAP

08/00