

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB No 1004-0137
Expires: October 31, 2014

JUN 21 2012

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
JIC34

6. If Indian, Allottee or Tribe Name
Jicarilla

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Four Star Oil & Gas Company

3a. Address
332 Road 3100
Aztec, NM 87410

3b. Phone No. (include area code)
505-333-1941

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
Jicarilla C 30

9. API Well No.
30-39-22841

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
990 FSL 990 FEL Sec 27 Twp 25N Rng 5W

10. Field and Pool or Exploratory Area
Otero Gallup

11. County or Parish, State
Rio Arriba, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Project is tentatively planned to begin July 15, 2012

1. Remove tubing.
2. Tag for fill and cleanout to PBTD @ 6535'.
3. Acidize existing Gallup zones 1673'-6506'. 6173'-6506'
4. Run production tubing and land at 6515'.
5. Run rods and new 2 stage HVR pump.
6. Install 320 gas engine pumping unit.

RCVD JUN 27 '12
OIL CONS. DIV.
DIST. 3

Accepted for Record

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)

April E. Pohl

Title Regulatory Specialist

Signature

April E. Pohl

Date

06-21-2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

JUN 25 2012

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

NMOCD *rv*



Jicarilla C30

Rio Arriba County, New Mexico

Sec 27 – T 25N – R 5W

Field: Basin

API: 30-039-22841

1. REMOVE TUBING.
2. TAG FOR FILL AND CLEANOUT TO PBTD @ 6535'.
3. ACIDIZE EXISTING GALLUP ZONES 6173'-6506'.
4. RUN PRODUCTION TUBING AND LAND AT ~ 6515'.
5. RUN RODS AND NEW 2-STAGE HVR PUMP.
6. INSTALL 320 GAS ENGINE PUMPING UNIT.

See Current Wellbore Diagram:

