Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No 1004-0137 Expires: October 31, 2014

JUN 21 2012 5. Lease Serial No.

|5. Lease Serial No. | NMNM78406C&D/NMSF079364

SUNDRY NOTICES AND REPORTS ON WELFL& Smington Field Of Mulf Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to creenter and Manageme.

abandoned well. Use Form 3160-3 (APD) for such proposals. 7 If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8 Well Name and No Oil Well ✓ Gas Well Other Rincon 149M 2. Name of Operator Chevron Midcontinent L.P. 9 API Well No. 30-039-25432 10 Field and Pool or Exploratory Area 3b Phone No. (include area code) 3a Address 332 Road 3100 Aztec, NM 87410 Basin Dakota MV 505-333-1941 4. Location of Well (Footage, Sec., T., R, M., or Survey Description) 11. County or Parish, State Rio Arriba, New Mexico 1900 FNL 1365 FWL Sec 30, Twp 27N Rng 6W 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Deepen Deepen Water Shut-Off ✓ Acidize Production (Start/Resume) ✓ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Install plunger lift New Construction Casing Repair Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Appproximate start of project is July 15, 2012 1. REMOVE TUBING. 2. TAG FOR FILL AND CLEANOUT TO PBTD @ 7700'. 3. ACIDIZE PRODUCING ZONES INCLUDING MESAVERDE (4902'-5542') AND DAKOTA (7566'-7634'). 4. RUN PRODUCTION TUBING AND LAND AT ~ 7610'. 5. INSTALL PLUNGER LIFT EQUIPMENT. RCVD JUN 27'12 OIL CONS. DIV. DIST. 3 April E. Pohl Title Regulatory Specialist 16-21-2012 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Original Signed: Stephen Mason IUN 2 5 2012 Date Conditions of approval, if any, are attached Approval of this notice does not warrant or certify

(Instructions on page 2)

entitle the applicant to conduct operations thereon

that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

Title 18 U.S C Section 1001 and Title 43 U.S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,



Rincon Unit 149M

Rio Arriba County, New Mexico Sec 30 – T 27N – R 6W Field: Basin API: 30-039-25432

- 1. REMOVE TUBING.
- 2. TAG FOR FILL AND CLEANOUT TO PBTD @ 7700'.
- 3. ACIDIZE PRODUCING ZONES INCLUDING MESAVERDE (4902'-5542') AND DAKOTA (7566'-7634').
- 4. Run production tubing and land at ~ 7610 '.
- 5. Install plunger lift equipment.

See Current Wellbore Diagram:

