

Form 3160-5
(April 2004)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0137
Expires: March 31, 2007

DIST. 3

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No NM SF 0081226
2. Name of Operator Bolack Minerals Company		6. If Indian, Allottee or Tribe Name
3a. Address 3901 Bloomfield Highway Farmington, NM 87401	3b. Phone No (include area code) (505) 325-4275	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec, T., R., M., or Survey Description) 1935' FSL and 860" FEL, Section 3 Township 30 North, Range 16 West, N.M.P.M.		8. Well Name and No Thomas F. Bolack #1 Well
		9. API Well No 3004532583
		10. Field and Pool, or Exploratory Area Wildcat McCracken
		11. County or Parish, State San Juan County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input checked="" type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input checked="" type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

(See attached Exhibit "A")

RECEIVED
 BLM
 210 FARMINGTON NM
 2007 DEC 29 AM 9:07
 Jan 03
 M.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Tommy Bolack		Title General Partner
Signature 		Date January 2, 2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by _____ Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Title _____ Office _____	Date _____ <p align="center">ACCEPTED FOR RECORD</p> <p align="center">JAN 04 2007</p> <p align="center">FARMINGTON FIELD OFFICE</p> <p align="center">BY </p>
--	-----------------------------	--

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2).

NMOCD

**EXHIBIT "A" TO
SUNDRY NOTICES AND REPORTS ON WELLS
OF
BOLACK MINERALS COMPANY
THOMAS F. BOLACK #1 WELL
DATED JANUARY __, 2007**

13. Describe Proposed or Completed Operation . . .

12/18/06 LAY DOWN DRILL PIPE & MONITOR WELL F/FLOW [NO FLOW] RU CSG CREW. ROLL CSG. XO RAMS T/7", & HOLD SFTY MTG W/DAY CREW & EVE CREW. RUN 7" CSG. FLOAT SHOE ON BOTTOM & FLOAT COLLAR ON TOP OF 1'ST JT, 34 JTS 23# N-80 ON BOTTOM, 9 JTS 20# J-55, DV TOOL, 106 JTS 20# J-55, 5 JTS 23# N-80 ON TOP, TOTAL 120 JTS 7" IN HOLE TOTAL LENGTH = 5386.27. FLOAT SHOE @ 5366', FC @ 5321', DV TOOL @ 3440'. CIRC CSG ON BOTTOM & SPOT IN RU BJ SVC. CMT 1'ST STAGE AS FOLLOWS, 20 BBLS H2O, 20 BBLS GELL H2O, 450 SX & ADDS. 14.2 # GAL 1.49 CU FT SK. DISPLACE W/214 BBLS DRILLING MUD, BUMP PLUG @ 3:18 A.M. DROP BOMB @ 3:20 AM, OPEN DV TOOL @ 3:50 AM, 729 PSI. CIRC HOLE BETWEEN STAGES. [CIRC OUT 20 BBLS GOOD CMT].

12/19/06 CIRC 7" CSG THRU DV TOOL @ 3440' BETWEEN STAGES. 2'ND STAGE CMT AS FOLLOWS. 10 BBLS FW, 10 BBLS GELLED H2O, LEAD SLURRY PREM LITE FM & ADDS, 500 SX 195 BBLS @ 12# PG, 2.19 CU FT SK. TAIL SLURRY 175 SX, 46 BBLS @ 14.2# PG. 1.49 CU FT SK. DISPLACE W/138 BBLS FW, CIRC OUT 75 BBLS GOOD CMT. BUMP PLUG & CLOSE DV TOOL @ 11:52 AM 12/20/2006. BUMPED PLUG W/2542#. [CMT JOB WITNESSED BY VAL JAMISON BLM FARMINGTON OFFICE] ND BOP & SET 90K ON 7" SLIPS. CUT OFF CSG & NU "B" SECTION AND BOPE.

12/20/06 TEST BLIND RAMS & 7" CSG @ 1500# 30 MIN OK. INSTALL TEST PLUG IN BRAIDEN HEAD & TEST BOP PIPE & BLIND RAMS, KILL LINE VALVES, MUD CROSS VALVES, CHOKE MANIFOLD VALVES, FLOOR VALVE, UPPER KELLY VALVE, STANDPIPE VALVE, ALL @ 250# LOW F/15 MIN EACH & 3000# HIGH F/15 MIN EACH. GOOD TEST ON ALL COMPONENTS, DRAIN BOPE & HOLD SAFETY MTG. PU BIT #8, 6-1/4" REED & TIH PU 20-5" DC'S & 3.5" DP.