

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS JUL 10 2012
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Fairington Field Office
Bureau of Land Management

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Golden Oil Holding Corporation

3a. Address
2000 Berring Drive, Suite 255, Houston, TX 77057

3b. Phone No. (include area code)
713-626-1110

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
900' FNL, 990 FEL, Section 3, T22N, R3W

5. Lease Serial No.
Jicarilla Apache Lease 54

6. If Indian, Allottee or Tribe Name
Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
No. 1 Jicarilla Apache 54

9. API Well No.
30-043-20349

10. Field and Pool, or Exploratory Area
SAN LINDRITH G1-DAKOTA

11. County or Parish, State
Sandoval County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RCVD JUL 13 '12
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

ROBERT Whiteley Agent

Title **DISTRICT MANAGER AAA Well Service**

Signature

Robert Whiteley

Date **7-10-12**

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date

JUL 12 2012
FAIRINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD A

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

DEC 09 2010

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
Jicarilla Apache Lease 54
6. If Indian, Allottee or Tribe Name
Jicarilla Apache

SUBMIT IN TRIPLICATE - Other instructions on page 2.

Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

Name of Operator
Golden Oil Holding Corporation

3a. Address
100 Spring Drive, Suite 255, Houston, TX 77057

3b. Phone No. (include area code)
713 626-1110

Location of Well (Footage, Sec., T., R., M., or Survey Description)
N° FLN & 990° FEL Sec 3, T 22N, R3W

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
No. 1 Jicarilla Apache 54

9. API Well No.
30-043-20349

10. Field and Pool or Exploratory Area
San Lindrith GI - Dakota

11. Country or Parish, State
Sandoval County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

3. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

We expect to initiate plug and Abandonment action on or about 3/25/11. See attached Plug and Abandonment Procedure*

RCVD DEC 13 '10

OIL CONS. DIV.

DIST. 3

4. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
Melinda Billon

Title Manager

Signature

Melinda L. Billon

Date

12-3-10

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

DEC 10 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Instructions on page 2)

NMOCD

0129

Day Tue

Company Golden oil

[illegible]

Fuel & Motor Oil	Water Hauled
-----------------------------	---------------------

Rental Equipment	Cement Retainers
-------------------------	-------------------------

Cementing

Wireline	
-----------------	--

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	38		
Operator	A. Reyes	75		11 1/2
Derrick	J. Jaramez			11 1/2
Floors	J. Alvarez			11 1/2
Floors	Juan Palermiano			11 1/2
Floors	D. Pape			11 1/2

Company GOLDSON OIL

Fuel & Motor Oil _____ Water Hauled 2-loads Fresh (J+S)
Rental Equipment _____ Cement Retainers 4 1/2" DHS @ 5764'
Cementing _____
Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	38		
Operator	A. Reyes	75		14
Derrick	J. Jaramez			14
Floors	J. Alvarez			14
Floors	Juan Palomino			14
Floors				

Rig No 114

Date 5-24-12 Day Thu

Well Name Jic Apache 54 #1

Company GOLDEN OIL

FROM	TO	DESCRIPTION OF OPERATION
5:00	5:15	LOAD RIG SUPPLYS.
5:15	7:15	TRAVEL TO Loc.
7:15	7:45	START RIG & EQUIP. HOLD SAFETY mts (TAPIC) JSA.
7:45	8:00	CHECK PSI ON WITH CSA TB9 & B-H O# OPEN WELL UP.
8:00		LOAD THE HOSE WITH 8 BBLS WATER CIRC CLEAR WITH ANOTHER 78 BBLS WATER TOTAL 86 BBLS. TRY TO TEST CSS. NO TEST PUMPING INTO HOLE @ 1 BPM @ 700#. Plug #1 mix & PUMP 24 SKS 28.3 CUFT TYPE B Cement ^{15.6"} , FROM 5744' TO TAC @ 5440'
	9:00	L-D TB9 TO 5407'. POOH IN STDS TO 4759'.
9:00	9:15	L-D TB9 TO 5407'. POOH IN STDS TO 4759'.
9:15	1:45	WOC.
1:45	2:00	TIT & TB9 TAC @ 5506'.
2:00	2:30	L-D TB9 TO 4207'.
2:30		LOAD THE HOSE WITH 7 BBLS WATER. TRY TO TEST CSS. NO TEST. Pumping INTO Hole @ 1 BPM @ 700#. Plug #2 mix & PUMP 24 SKS 28.3 CUFT TYPE B Cement ^{15.6"} , FROM 4207' TO TAC @ 3883'.
	3:00	TO TAC @ 3883'.
3:00	3:30	L-D TB9 TO 2659'.
3:30	4:00	POOH WITH TB9 & L-D SETTING TOOL.
4:00	4:30	SWE SECURE LOC. SDEA.
4:30	6:30	TRAVEL TO YARD.
		(13 1/2 HRS)
		Total HAASSTON w/BLM as loc.

Fuel & Motor Oil _____ **Water Hauled** 2 Loads Fresh (J+S)

Rental Equipment _____ **Cement Retainers** _____

Cementing P-#1-24 SKS ^{15.6#} P-#2-24 SKS ^{15.6#}

Wireline

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	38		
Operator	A. Reyes	75		13 1/2
Derrick	J. JARQUEZ			13 1/2
Floors	J. AREVALO			13 1/2
Floors	Juan Ramirez			13 1/2
Floors				

AAA WELL SERVICE, LLC

401 Bloomfield Hwy • Farmington, NM 87401
505-436-2351 • Fax: 505-436-2354

0132

Rig No 114Date 5-25-12 Day FriWell Name Jic Apache 54 #1Company Golden rule

FROM	TO	DESCRIPTION OF OPERATION
5:00	5:30	LOAD RIG SUPPLIES
5:30	7:30	TRAVEL TO LOC.
7:30	8:00	START RIG & EQUIP. HOLD SAFETY MEET (TOPIC) TSA.
8:00	8:15	CHECK PSI ON W-L, CS9 & B-H 1", AIA TB9 IN W-L. OPEN W-L UP.
8:15	8:30	LOAD THE HOLE WITH 9 BBL WATER. TEST CS9 TO 800" HOLD 10 MIN OK.
8:30		R-U W-L (BASIN) T-H & TB9 TO 3905' P-U HOLE & PERF 3 HSC HOLES @ 2712'
		PUGH R-D W-L TRY TO EST RATE INTO PERFS @ 2712' PUMP 1/2 BBL WATER. PRESSURE UP
	9:15	& HOLD 1300"
9:15	9:45	T-H WITH TB9 TO 2788'
9:45		HOLE STANDING STILL. PLUG #3 MIX & PUMP 43 SKS 50.7 CUST TYP. B CEMENT, FROM 2788'
	10:15	TO LOC @ 2707'
10:15	11:00	1-D TB9 TO 1108'
11:00	11:30	PUGH WITH TB9
11:30		R-U W-L T-H & PERF 3-HSC HOLES @ 1162'. PUGH R-D W-L R-D LOAD THE HOLE WITH 5 BBL
	11:50	WATER. EST RATE INTO PERFS @ 1162' @ 1 BPM @ 1000"
11:50	12:15	T-H & SET 4 1/2" DHS RET @ 1108'
12:15		EST RATE INTO PERFS @ 1162' @ 1 BPM @ 1100". PLUG #4 MIX & PUMP 55 SKS 64.9 CUST
		TYP. B CEMENT WITH 43 SKS 50.7 CUST BELOW RET & 12 SKS 14.2 CUST ON RET. TO @
	12:45	946'
12:45	1:15	1-D ALL THE TB9 & SETTING TOOL.
1:15	1:45	R-U W-L T-H & PERF 3-HSC HOLES @ 319'. PUGH R-D W-L
1:45		LOAD THE HOLE & BREAK CIRC OUT THE R-H. PLUG #5 MIX & PUMP 123 SKS 145.1 CUST
	2:30	TYP. B CEMENT, FROM 319' TO SURF WITH GOOD CEMENT RETURNS OUT THE R-H. SURF
2:30	3:00	SECURE LOC SOPS.
3:00	5:00	TRAVEL TO YARD.
		(12 HRS)
		MIKE GILBREATH w/BLM ON LOC.

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers 4 1/2" DHS @ 1108'Cementing 9-#3-43 SKS P-#4-55 SKS P-#5-123 SKSWireline 3-HSC HOLES @ 2712' & 1162' & 319' (BASIN)

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	38		
Operator	A. Reyes	75		12
Derrick	J. Jaquez			12
Floors	J. Arcevala			12
Floors	JUAN PALOMINO			12
Floors				

Rig No 114

Date 5-29-12 Day Tue.

Well Name JIC Apache 54th

Company Garden oil

FROM	TO	DESCRIPTION OF OPERATION
5:00	5:30	Load Rig Supplies
5:30	7:30	Travel To Loc.
7:30	8:00	START Rig + equip. Hold SAFETY MEET (Topic) JSA.
Rig	10:00	P-2 1 JT + TAG TAC 9' from SURF. L-D 1 JT. R-D TBG equip + Rig Floor. AT-D BOP.
10:00	2:00	DIG OUT W-H. CUT OFF. W-H. INSTANT MARKER WITH 28 SPS CEMENT
2:00	4:00	R-D Rig + cement equip CUT OFF Anchors safely.
4:00	6:00	Travel To Yard.
		(13 HRS)

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ **Cement Retainers** _____

Cementing marks 28 sks

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	38		
Operator	A. Reyes	75		13
Derrick	J. JAGUEZ			13
Floors	J. AREVALO			13
Floors	J. Pineda			13
Floors				