## RECEIVED

INITED STATES

AU5 U 1 2012

DEMERSION FIELD OFFICE

rom 3160- 5	UNITED	SIAIES	nn 91700		FORM APPROVED
(August 2007)	DEPARTMENT OF	THE INTERIOR	JUL 31 ZUIZ		OMB No 1004-0137
			Cald Off	·C-	Expires July 31,2010
	BUREAU OF LAND	Fa	rmington Field Chin	Lease Serial N	ío
	SUNDRY NOTICES AND REPORTS ON WELL SLand Mana			Contract 460	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee, or Tribe Name	
				Jicarilla Apache Tribe	
SUBMIT IN TRIPLICATE - Other Instructions on page 2.					Agreement Name and/or No.
1. Type of Well	IN TRIFEICATE - Other IIIs	urucuons on page 2.			
Oil Well Gas Well	Other		8	Well Name an	d No
2. Name of Operator				Jicarilla	460 #2
Black Hills Gas Resources, Inc.				API Well No.	
3a. Address 3b Phone No (include area code)				30-039-24112	
3200 N 1st St, Bloomfield, NM 87413 (505) 634-5104				10. Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec, T, R, M, or Survey Description)				E.BlancoPC & CabrestoCanyonTert.	
790' FSL & 890' FWL SW/SW, Section 21, T30N R3W (UL: M)				11 County or Parish, State	
				Rio Arriba County, New Mexico	
12 CHECK A DD	DODDLATE DOVING TO BIDL	CAMENIAMINE OF N	OTICE DEPONT OF		
	PROPRIATE BOX(S) TO INDIC	CATE NATURE OF N	OTICE, REPORT, OR	OTHER DA	NIA
TYPE OF SUBMISSION	TYPE OF ACTION				
		1_			
Notice of Intent	Acidize	Deepen	Production ( Start	(Resume)	Water Shut-off
	Altering Casing	Fracture Treat	Reclamation		Well Integrity
[7] <sub>-</sub>			=		
Subsequent Report	Casing Repair	New Construction	Recomplete		Other
aD.	Change Plans	Plug and abandon	Temporarily Aban	don	
		J			
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal		
If the proposal is to deepen directi- Attach the Bond under which the vifollowing completion of the involvesting has been completed. Final determined that the site is ready for	Operation Clearly state all pertment detail ionally or recomplete horizontally, give si work will performed or provide the Bond ved operations. If the operation results in Abandonment Notice shall be filed only a final inspection.)  arces has plugged & abando	ubsurface locations and meas No. on file with the BLM/ B a multiple completion or rece after all requirements, includi	ured and true vertical depths o IA Required subsequent report completion in a new interval, a ing reclamantion, have been co	f all pertinent n rts shall be filed Form 3160-4 sh	narkers and zones I within 30 days all be filed once
	is true and correct. Name (Printed/ Type	·	Taskisis		
Daniel Manus	Title	y Techician			
Signature Lawie	Vanvs		13/2012	***	ASSEPTED FOR REQUE

that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify

Approved by

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Office



## **Black Hills Gas Resources**

## Jicarilla 460 #2

Surface Location: 790' FSL 890' FWL (SW/SW) Sec.21 T30N R3W Lease: Contract 460

## Plugged & abandoned Procedure

7/03/12: 9:15 AM, Notified BLM, NMOCD, JAT-BLM of upcoming operations.

- 7/05/12: MIRU A Plus Well Service Rig #5. SICP 0 PSI & SIBHP 0 PSI. Dig out BH valve. No csghead, 7 5/8" folded in & welded to 4 ½" csg. ND WH. NU BOP & function test. PU & TIH with bit, collars & workstring. SDFN.
- 7/06/12: SITP 0 psi. SICP 0 psi. SIBHP 0 psi. MI H2S trailer. Ream 3011-3025'. Drill out CIBP at 3025'. Tag at 3204'. Drill on CIBP junk & CBP. SDFN.
- 7/09/12: SITP & SICP on vac. SIBHP 0 psi. 0 H2S. TOH. Bit missing cones. Run magnet on sandline, 5 trips. Recover iron & steel. Run magnet on workstring. No recovery. SDFN.
- 7/10/12: SICP on vac. SIBHP 0 psi. TIH with mill to 3206'. Drill out CBP. Circ well at 3 bpm. Losing 1 bpm to well. TIH & tag at 3661'. WOO. Receive approval from Brandon Powell, NMOCD & Bryce Hammond, BLM at 2:30 PM to spot plug # 1 from 3661'. TOH with bit. SDFN.
- 7/11/12: SICP on vac. SIBHP 0 psi. TIH. Receive approval from Brandon Powell, NMOCD & Bryce Hammond, BLM at 9:00 AM to spot plug # 1 from 3661'. Mix & spot Cmt Plug #1 (32 sx, 37.8 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt, 2% CaCl2) inside csg from 3661' to 3228'. TOH. WOC. Tag plug #1 at 3264'. Receive approval from Brandon Powell, NMOCD & Bryce Hammond, BLM at 2:00 PM to combine plugs #2 & #3. TIH, set 4 ½" CR at 3174'. Test tbg to 1500 psi, ok. Sting out. Mix & spot Cmt Plug #2 (37 sx, 43.7 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) inside csg from 3174' to 2674'. TOH. SDFN. Bryce Hammond, JAT-BLM on location.
- 7/12/12: SICP 0 psi. SIBHP 0 psi. TIH, tag plug #2 at 2720'. TOH. Load 4 ½ csg with 6 ¼ bbls. Bled 700 psi to 550 psi in 1 min. Perf csg at 1976' with 3 holes. Est rate down csg at 1 bpm, 650 psi. TIH, set 4 ½" CR at 1945'. Test tbg to 1500 psi, ok. Sting out. Press test csg to 750 psi, held ok. Sting into CR. Mix & pump Cmt Plug #3 (39 sx, 46 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt). Pump 27 sx below CR, 1 bpm, 600 psi final. Sting out. Leave 12 sx inside csg from 1945' to 1783'. TOH. Load csg with 3 bbls. Test csg to 700 psi, held ok. Perf csg at 191' with 3 holes. Est rate thru perfs at 2 bpm, 600 psi. Est circ out BH valve with 4 bbls. Mix & pump Cmt Plug #4 (49 sx, 57.8 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) from 191' to surface. Circ cmt returns out BH valve. WOC. SDFN. Bryce Hammond, JAT-BLM on location.
- 7/13/12: TOC at 6' in 4 ½ csg. ND BOP. Cut off wellhead. TOC in 4 1/2" x 7 5/8" annulus at surface. RD rig. Mix & pump 10 sx, 11.8 cu ft, 15.6# class B cmt & set DH marker. Release A Plus Rig # 5. Bryce Hammond, JAT-BLM on location.