

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report



Name of Company: BP America Production Company	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Hutchin LS 1	Facility Type: Natural Gas Well	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 300450795000

**LOCATION OF RELEASE**

Unit Letter N	Section 19	Township 29N	Range 08W	Feet from the 990	North/South Line South	Feet from the 990	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	--------------------

Latitude 36.7065 Longitude 107.72004

**NATURE OF RELEASE**

Type of Release: Natural Gas	Volume of Release: 102 MCF	Volume Recovered: none
Source of Release: PSV	Date and Hour of Occurrence: 11 pm - 8 am on 8/19/2012	Date and Hour of Discovery: 8/19/2012
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <div style="text-align: right;"><b>RCVD AUG 30 '12 OIL CONS. DIV. DIST. 3</b></div>		
Describe Cause of Problem and Remedial Action Taken.* Pressure safety valve on fuel start gas found lifting. Suction control valve was wide open and not restricting the recycled pressure thus causing the PSV to lift. Compressor has been isolated and an investigation started.		
Describe Area Affected and Cleanup Action Taken.* Natural gas dissipated to atmosphere, so no clean-up action possible.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 9/06/2012	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/23/2012	Phone: 505-326-9457	

\* Attach Additional Sheets If Necessary

NJK1225049579