

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well ☐ Oil Well ☒ Gas Well ☐ Other		5. Lease Serial No NMNM0557296A
2. Name of Operator DUGAN PRODUCTION CORPORATION		6. If Indian, Allottee or Tribe Name
Contact ALIPH REENA Email: aliph.reena@duganproduction.com		7. If Unit or CA/Agreement, Name and/or No
3a. Address FARMINGTON, NM 87499	3b. Phone No. (include area code) Ph: 505-325-1821	8. Well Name and No OLD HICKORY 2
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 33 T26N R12W NWSE 1500FSL 1600FEL 36.441391 N Lat, 108.112717 W Lon		9. API Well No 30-045-21853-00-S1
		10. Field and Pool, or Exploratory UNDESIGNATED
		11. County or Parish, and State SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plan to plug and abandon the well by the following procedure:

- 1) Pump ?10 bbl water down the casing to establish rate.
- 2) Fill 2-7/8" production casing with 40 sks (47.2 cu ft) Type III neat cement from surface to perforations.
- 3) Pump Type III neat cement through 1" poly-pipe to fill the surface casing-production casing annulus to surface.
- 4) Tag cement top at surface.
- 5) Install dry hole marker.

Notify NMOCD 24 hrs
prior to beginning
operations

RCVD SEP 21 '12
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct.	
Electronic Submission #150137 verified by the BLM Well Information System For DUGAN PRODUCTION CORPORATION, sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 09/19/2012 (12SXM0323SE)	
Name (Printed/Typed) ALIPH REENA	Title PRODUCTION ENGINEER
Signature (Electronic Submission)	Date 09/13/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By STEPHEN MASON	Title PETROLEUM ENGINEER	Date 09/19/2012
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon		Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

NMOCD *AL*