

District I
1625 N French Dr , Hobbs, NM 88240
District II
811 S. First St , Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Ashley Maxwell	
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-324-5169	
Facility Name San Juan 27-4 Unit 56N	Facility Type Gas Well	
Surface Owner Federal	Mineral Owner Federal	API No. 3003931105 Lease # SF-080671

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	027N	004W	1791'	South	1360'	West	Rio Arriba

Latitude 36.556551 Longitude -107.259942

NATURE OF RELEASE

Type of Release Drilling Mud	Volume of Release 5 BBL	Volume Recovered 5 BBL
Source of Release Suction Hose	Date and Hour of Occurrence 7/2/2012 @ 12:00PM	Date and Hour of Discovery 7/2/2012 @ 12:00PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD OCT 1 '12 OIL CONS. DIV. DIST. 3	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The suction hose on pump #1 spilt creating a 5 BBL spill of drilling mud. 5 BBL of drilling mud was recovered using a vacuum pump. Hose was removed and put out of service.		
Describe Area Affected and Cleanup Action Taken.* The spill was limited to the mud pump area & containment ditches. COPC will assess the soil and determine a path forward for clean-up, if necessary. A COPC third party contractor was responsible for the clean up of this spill. The drilling mud was removed using a vacuum truck. During a follow up site visit no staining or crusting was observed on location. Therefore, no further action was taken.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ashley Maxwell	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: <u>10/23/2012</u>	Expiration Date:
E-mail Address: ashley.p.wethington@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 27, 2012 Phone: 505-324-5169		

* Attach Additional Sheets If Necessary

nJK1229734139