PN

• •	,
Submit, 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION	30-031-21055
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Pio Prozos Pd. Astes. NM 97410	STATE FEE 🔀
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Tanner Tank SF 22
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number #1
	9. OGRID Number 162683
2. Name of Operator	9. OGRID Number 102083
3. Address of Operator	10. Pool name or Wildcat
3. Address of Operator P.O. Box 140907 Irving, TX 75014-0907	WC20N7W22; Meneffee Gas 97307
1.0. box 140507 Hving, 1A 73014-0707	WC2011/W22, Menence Gas 9/30/
4. Well Location	- 12
by the state of th	833 feet from the <u>East</u> line
Unit Letter A: 830 feet from the North line and	
Section 22 Township 20N Range 07	NMPM County McKinley
11. Elevation (Show whether DR, RKB, RT, GR)	etc.)
6584 GR	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls;	Construction Material
12. Check Appropriate Box to Indicate Nature of Noti	se Report or Other Data
12. Check Appropriate Box to indicate Nature of Noti	ce, Report of Other Data
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	ORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE	ORK ☐ ALTERING CASING ☐ DRILLING OPNS.☐ P AND A ☑
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	ORK ☐ ALTERING CASING ☐ DRILLING OPNS.☐ P AND A ☑
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE	ORK ☐ ALTERING CASING ☐ DRILLING OPNS.☐ P AND A ☑
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER:	ORK
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM	ORK ALTERING CASING DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details	ORK ALTERING CASING DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions:	ORK ALTERING CASING DRILLING OPNS. P AND A ENT JOB and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions:	ORK ALTERING CASING DRILLING OPNS. P AND A ENT JOB Daniel Drive pertinent dates, including estimated date Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB Driver and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB Driver and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB Dand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description of the proposed completion at 404'.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB Dand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description of the proposed completion at 404'.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. from 404' to surface, circulate good
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB DRILLING OPNS. PAND A ENT JOB Dand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. From 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A marketers.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB DRILLING OPNS. PAND A ENT JOB Dand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. From 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB Dand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Days wellhead. Perforate 3 holes at 404'. from 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A marketers.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB DRILLING OPNS. PAND A ENT JOB Dand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. From 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB Driver and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. From 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowledge.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB DRILLING OPNS. PAND A ENT JOB DATE and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. From 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB DRILLING OPNS. PAND A ENT JOB DATE and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. From 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowledge.	ORK ALTERING CASING DRILLING OPNS. PAND A ENT JOB DRILLING OPNS. PAND A ENT JOB DATE and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 23, 2004. Description wellhead. Perforate 3 holes at 404'. from 404' to surface, circulate good and down 10' in the annulus.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowlegrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Agent	ORK
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowlegrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Agent	ORK
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowl grade tank has been/will be constructed or closed according to NMOCD guidelines \(\), a general permit SIGNATURE Bret Cook E-mail address: bret.cook@cdxgas.com E-mail address: bret.cook@cdxgas.com	ORK
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowl grade tank has been/will be constructed or closed according to NMOCD guidelines \(\), a general permit SIGNATURE Bret Cook E-mail address: bret.cook@cdxgas.com E-mail address: bret.cook@cdxgas.com	ORK
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowl grade tank has been/will be constructed or closed according to NMOCD guidelines \(\), a general permit SIGNATURE Bret Cook E-mail address: bret.cook@cdxgas.com E-mail address: bret.cook@cdxgas.com	ORK
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Gruy Petroleum Management Co. plugged and abandoned this well on November 11/23/04 Drive cementing equipment to location and RU. RU A-Plus wireline unit. N Establish circulation to surface with 10 bbls of water at 2.5 bpm at 150#. Plug #1 with 124 sxs Type III cement (164 cf) pumped down the 5.5" casing cement out the bradenhead. Dig out and cut off the wellhead. Found cement down 5' in the 5.5" casing a Mix 10 sxs cement to fill the casing and annulus and then install P&A market RD cementing equipment and MOL. I hereby certify that the information above is true and complete to the best of my knowlegrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Agent	ORK