



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

April 22, 2005

Dolores Silseth
Burlington Res O&G Co
PO Box 4289
Farmington NM 87499

Re: San Juan 29-4 Unit 59, G-04-27N-04W, API # 30-039-20369

Dear Dolores

The 2004 Bradenhead test and 2005 retest on the above well indicate a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before July 31, 2005.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top. Provide gas analysis from both the production and intermediate casing.

Reference RBDMS CTP0511235029 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
District III Supervisor
cperrin@state.nm.us

CTP/mk

CC: Well File