



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

May 24, 2005

Juanita Farrell
ConocoPhillips Company
5525 Hwy 64
Farmington, NM 87401

RE: San Juan 32-7 #13, N-16-32N-07W, API 30-045-11387

Dear Juanita:

The 2005 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to conduct remedial activity before August 25, 2005.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top. Provide gas analysis from both the production and intermediate casing.

Reference RBDMS CTP0514331287 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
District III Supervisor
cperrin@state.nm.us

CTP/mk

CC: Well file
CP