UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells		
	5.	Lease Number
		NMSF-080712A
Type of Well GAS	6.	If Indian, All. or Tribe Name
	7.	VI-24 A 4 NI
Name of Operator	7.	Unit Agreement Name
BURLINGTON AND AND AND AND AND AND AND AND AND AN	λ	San Juan 30-6 Unit
RESCURCES OIL & GAS COMPANY LP	À	San Suan 50-0 Cait
	8.	Well Name & Number
Address & Phone No. of Operator	Ĵ	#480
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
		30-039-24488
4. Location of Well, Footage, Sec., T, R, M Sec., TN, RW, NMPM	10.	Field and Pool
790' FNL & 1305' FEL, Section 30, T30N, R6W, NMPM		1 Fruitland Coal
	11.	County and State Rio Arriba Co., NM
Kasing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		
Describe Proposed or Completed Operations undry dated 4/4/05 on previous work when casing leak was found.		
5 RIH & dumped sand on RPB @ 2862'. TIH w/treating packer & set @ 735'. RU BJ ased pkr & POOH. Spot balance plug of cement across bad casing from 1376' – 750' w/ hole w/2-1/2 bbls & squeezed cement w/1500 psi. Squeezed approx. 4 sx. Left 1500 psi decement @ 837'. D/O cement from 837' – 1265'. Circ. hole clean. Test top 300 of ce 1265' – 1575' Circ. hole. PT casing to 500 psi / 30 min. No Leaks. BLM witnessed (J. R. C/O sand & retrieved RBP. POH & LD. C/O to PBTD @ 3126'. TIH & land tbg @ ed out. Load tbg & test tbg to 1000 psi – OK. RD & released rig 4/9/05.	120 sx (29 si on casin ment to 10 Ruybalid).	bbl slurry) Type III Neat. PO g. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N @ 3100' RIH w/pump & ro
ased pkr & POOH. Spot balance plug of cement across bad casing from 1376' – 750' w. hole w/2-1/2 bbls & squeezed cement w/1500 psi. Squeezed approx. 4 sx. Left 1500 psd cement @ 837'. D/O cement from 837' – 1265'. Circ. hole clean. Test top 300 of ce 1265' – 1575' Circ. hole. PT casing to 500 psi / 30 min. No Leaks. BLM witnessed (J. R. C/O sand & retrieved RBP. POH & LD. C/O to PBTD @ 3126'. TIH & land tbg @ ed out. Load tbg & test tbg to 1000 psi – OK. RD & released rig 4/9/05.	120 sx (29 si on casin ment to 10 Ruybalid).	bbl slurry) Type III Neat. PO g. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N @ 3100' RIH w/pump & ro
ased pkr & POOH. Spot balance plug of cement across bad casing from 1376' – 750' whole w/2-1/2 bbls & squeezed cement w/1500 psi. Squeezed approx. 4 sx. Left 1500 psd cement @ 837'. D/O cement from 837' – 1265'. Circ. hole clean. Test top 300 of ce 1265' – 1575' Circ. hole. PT casing to 500 psi / 30 min. No Leaks. BLM witnessed (J. R. C/O sand & retrieved RBP. POH & LD. C/O to PBTD @ 3126'. TIH & land tbg @ ed out. Load tbg & test tbg to 1000 psi – OK. RD & released rig 4/9/05.	(120 sx (29 si on casin ment to 10 Ruybalid).	bbl slurry) Type III Neat. PO g. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N@3100' KIH w/pump & ro
ased pkr & POOH. Spot balance plug of cement across bad casing from 1376' - 750' w. hole w/2-1/2 bbls & squeezed cement w/1500 psi. Squeezed approx. 4 sx. Left 1500 p ad cement @ 837'. D/O cement from 837' - 1265'. Circ. hole clean. Test top 300 of ce 1265' - 1575' Circ. hole. PT casing to 500 psi / 30 min. No Leaks. BLM witnessed (J. R. C/O sand & retrieved RBP. POH & LD. C/O to PBTD @ 3126'. TIH & land tbg @ ed out. Load tbg & test tbg to 1000 psi - OK. RD & released rig 4/9/05.	(120 sx (29 si on casin ment to 10 Ruybalid). 31223 w/S	bbl slurry) Type III Neat. POg. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N @ 3100' RIH w/pump & roll of the control
ACCEPTED FO Thereby certify that the foregoing is true and correct. ACCEPTED FO MAY 25	(120 sx (29 si on casin ment to 10 Ruybalid). 3122, w/S	bbl slurry) Type III Neat. PO g. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N @ 3100' RIH w/pump & ro
ased pkr & POOH. Spot balance plug of cement across bad casing from 1376' - 750' w. hole w/2-1/2 bbls & squeezed cement w/1500 psi. Squeezed approx. 4 sx. Left 1500 p ad cement @ 837'. D/O cement from 837' - 1265'. Circ. hole clean. Test top 300 of ce 1265' - 1575' Circ. hole. PT casing to 500 psi / 30 min. No Leaks. BLM witnessed (J. R. C/O sand & retrieved RBP. POH & LD. C/O to PBTD @ 3126'. TIH & land tbg @ ed out. Load tbg & test tbg to 1000 psi - OK. RD & released rig 4/9/05. ACCEPTED FO MAY 25	(120 sx (29 si on casin ment to 10 Ruybalid). 3122, w/S	bbl slurry) Type III Neat. PO g. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N@3100' RIH w/pump & ro
ACCEPTED FO I hereby certify that the foregoing is true and correct. ACCEPTED FO MAY 25 Title Sr. Regulare Assumed plug of cement across bad casing from 1376' - 750' w. hole w/2-1/2 bbls & squeezed cement w/1500 psi. Squeezed approx. 4 sx. Left 1500 psi document @ 837'. D/O cement from 837' - 1265'. Circ. hole clean. Test top 300 of ce 1265' - 1575' Circ. hole. PT casing to 500 psi / 30 min. No Leaks. BLM witnessed (J. I. C/O sand & retrieved RBP. POH & LD. C/O to PBTD @ 3126'. TIH & land tbg @ ed out. Load tbg & test tbg to 1000 psi - OK. RD & released rig 4/9/05. ACCEPTED FO MAY 25 Title Sr. Regulare Title Sr. Regulare	(120 sx (29 si on casin ment to 10 Ruybalid). 3122, w/S	bbl slurry) Type III Neat. POg. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N @ 3100' RIH w/pump & room of the company
ACCEPTED FO Thereby certify that the foregoing is true and correct. ACCEPTED FO MAY 25	(120 sx (29 si on casin ment to 10 Ruybalid). 3122, w/S	bbl slurry) Type III Neat. PC g. WOC. 4/5/05 RIH w/bit & 00 psi – Held good, D/O ceme TIH & tagged 6' sand on top N @ 3100' RIH w/pump & r