In Lie	u of
Form	3160
(June	1990)

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31 1993

If Indian, Allottee or Tribe Name

SUNDRY NO	TICE AND	DEDUDLE	ON WEI	1 9

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

 Lease Designation and Serial No. SF-078767

6.

	SUBMIT IN TRIPLICATE	A 28 28 30 370 7	7.	If Unit or CA, Agreement Designation
1.	Type of Well Oil Well X Gas Well Other	MAY	8.	Well Name and No. ROSA UNIT #210
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	77772. 60 70 70 80 80 80 80 80 80 80 80 80 80 80 80 80	:⊽≅⊽:: 5	API Well No. 30-039-24523
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		.γιο. -	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 1025 FSL & 1310 FWL, SW/4 SW/4 SEC 13-T31N-R06W	Wall Spirit	11.	County or Parish, State RIO ARRIBA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment	Altering Casing	Conversion to Injection	
	Other Pumping Unit & Rod Installation	Dispose Water	
		(Note: Report results of multiple completion	
		on Well Completion or Recompletion Report	
		and Log form.)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

04-26-2005 MIRU.

04-27-2005 Csg press 15#, BD to FB tank, ND tree, NU BOP, RU floor, pull tbg hanger, PU singles & tag up. PU off bottom, test lines 2000#, est circ w/ 12 bph mist. CO 7' of fill, bypass air. PU 50', wait on fill, tag up same spot, no fill. Tally 2 ½" tbg on TOOH, 96 jts, 1.81" F-nipple, 1 jt tbg, notched collar, total = 3045.76'. PU add 54' to CO (PBTD @ 3105'), rabbit tbg on TIH after MU w/ 100' sash cord. TiH as follows: 2 ½", 4.7#, J-55 mud anchor, 2 ½" x 1.78" F-nipple, 96 jts 2 ½", 4.7#, J-55 tbg, 6' pup jt, 1 jt 2 ½", 4.7#, J-55 tbg, MA landed @ 3102', 1.78" F-nipple @ 3073' w/ KB correction. RD floor, ND BOP, NU B-1 adapter, change over to run rods, SDFN.

<u>04-28-2005</u> Csg press 800#, tbg press 850#, BD to FB tank, kill tbg w/ 20 bbl prod. water, NU flow-T. PU rods & TIH as follows: 6' x 1" gas anchor, 2 x 1 /14 x 8 x 12 RHACZ pump w/ top hold down (82" max stroke), 4' pony, 122 – ¾" rods, 8' pony, 1 ½" x 22' polish rod w/ 1 ½" x 10' liner. MU stuffing box, seat pump, load tbg & test to 500# w/ rig pump, bleed off, stroke pump w/ rig, press to 500# for 15 mins, set tag, hang rods on unit. RD FB tank, pump, pit & derrick, release rig @ 1500 hrs, 4/28/05.

		ACCEPTED FOR RECC	ORD	
		MAY 2 7 2005	070	55 MAY
14.	I hereby certify that the foregoing is true and correct Signed Tracy Ross	Title Sr. Production Analyst Date	May 17, 2005	- 18 - 18
	(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	Date	9 17

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.