UNITED STATES DEPARTMENT OF THE INTERIOR Form 3160-5 BUREAU OF LAND MANAGEMENTJUN 22 (June 1990) Expires March 31, 1993 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED Do not use this form for proposals to drill or to deepen or reentry to a different reserve NMNM013885 Use "APPLICATION FOR PERMIT -" for such proposals? 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE 1. Type of Well 7. If Unit or CA, Agreement Designation Oil Well Gas Well Other **Federal** 8. Well Name and No. 2. Name of Operator Federal 29-12-24 #101 Synergy Operating, LLC 9. API Well No. 3. Address and Telephone No. 30-045-32852 P.O. Box 5513, Farmington, NM 87499 10. Field and Pool, or Exploratory 4. Location of Well (Footage, Sec, T. R., M, or Survey Description) **Basin Fruitland Coal** 1955' FSL, 885' FWL, Sec 24, T29N-R12W (Unit Ltr : L) 11. County or Parish, State San Juan Co., NM 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Abandoment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off **Final Abandonment Notice** Altering Casing Converion to Injection Other Dispose Water (Note: Report results of multiple completton on Well Completion or recompletion Report and Log Form) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work. 5-31-05: MIRU Blue Jet. Run GR-CCL Log F/1769'(PBTD) - T/1300'. BJ Svcs PT 5-1/2" 15.5# casing to 1500# for 30-Minutes per NMOCD, OK. PT 5-1/2" 15.5# casing to 3500# for 10-minutes, for frac, OK. Perf 1st Stage Fruitland Coal: Zone # 1 - 1690-94' (4') w/ 4-SPF, Zone #2 - 1678-86' (8') w/ 2-SPF, 32-Holes. Acidize perfs @ 1678-94' w/ 500-gals 7.5% HCl & 56-Ball sealers, ISIP = 750#. RIH w/ junk basket & recover 56-ball sealers. RD Blue Jet W/L. 6-1-05:

6-1-05: MIRU BJ Services. Fracture Stimulate 1st Stage FTC F/1678' -T/1694' w/ 15,246-gals 20# XL Gel, 27,000# 20/40 Brady SD @ 31.4-BPM, ATP=1613#. ISIP 544#. Set CIBP # 1 @ 1658'. PT CIBP to 1000#, OK. Perforate 2nd Stage FTC, Zone # 3 - 1644-48' (4'), Zone # 4 - 1623-28' (5') w/ 4-SPF, 36 holes. Unable to frac 2nd Stage due to sand fill at 1615'. Perforate 3rd Stage FTC, Zone # 5 - 1542-50' (8') w/ 4-SPF, Zone # 6 - 1517-19' (2') 4-SPF, 40-holes. Fracture Stimulate 3rd Stage FTC F/1517-T/1550', w/ 29,454 gals 20# XL Gel, 74,720# 20/40 Brady SD @ 29.8-BPM,

ATP=1362#. ISIP 911#.

6-17-05: MIRU Basic Energy rig #1510. NU 5-1/2" tbg head, companion flange & BOPE. TIH w/ 4-3/4" bit to 100'. SION.

6-18-05: TIH & CO sand fill F/1537' - T/1658' (CIBP). TOOH. TIH w/ pkr on tbg & set @ 1596' & breakdown perfs F/1623-T/1644' @ 3200#, pumped 120-Bbls 2% KCl wtr into perfs. TOOH w/ pkr. TIH w/ 4-3/4" bit & drill on CIBP @ 1658' for 2-1/4 Hrs, incomplete. PUH. SION

6-20-05: TIH & cont. DO CIBP @ 1658', cont. TIH & CO sand fill & cmt to FC @ 1785' w/ air/mist. Circ hole clean. TOOH w/
4-3/4" bit & LD DC's. Ran & landed 53-Jts 2-3/8" 4.7# J-55 & MA w/ EOT @ 1746' & SN @ 1728'. ND BOPE. RIH
w/ 2" x 1-1/4" x 12' x 12' RHAC pump on 4 - 1-1/4" sinker bars, 64 - 3/4" rods, space out pump. NU flow-tee & stuffing
box on 1-1/4" x 16' polish rod w/ 1-1/4" x 1-1/2" x 8' polish rod liner. PT pump to 500#, OK. RD rig.

14. I hereby certify that the foregoing is true and correct Signed:	Operations Manager	ACCEPTED FOR RECORD
This space for federal or state office use		
Approved by:	Title:	Date JUN 2 4 2005 FARMINGTON FIELD OFFICE