₱ submitted in lieu of Form 3160-5 UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 7505 JUN 24 PM 2 02 Sundry Notices and Reports on Wells RECEIVED Lease Number 070 FARMINGTON 51M SF-079193 If Indian, All. or 1. Type of Well Tribe Name GAS Unit Agreement Name 2. Name of Operator San Juan 28-6 Unit BURLINGTON SOURCES OIL & GAS COMPANY Well Name & Number 3. Address & Phone No. of Operator San Juan 28-6 Unit #127M PO Box 4289, Farmington, NM 87499 (505) 326-9700 API Well No. 30-039-27815 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool Surface 1515'FSL, 1585'FEL, Sec. 20, T28N, R6W, NMPM Blanco Mesaverde/Basin Dakota Bottom Hole: 2274' FSL, 95' FEL, Sec. 20, T28N, R6W 11. County and State Rio Arriba Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Non-Routine Fracturing Plugging Back Casing Repair _ Water Shut off Altering Casing Final Abandonment _ Conversion to Injection _X_ Casing Sundry 13.Describe Proposed or Completed Operations Please see attached sundry information. - Please submit the final deviation survey with completion report. I hereby certify that the foregoing is true and correct. Signed Title Regulatory Specialist Date 6/22/05 ACCEPTED FOR RECORD

(This space

APPROVED BY

CONDITION OF APPROVAL, if any:

for Federal or State Office use)

_Title

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or apencunited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Date

ency of UN 2 7 2005

FARMINGIUM FIELD OFFICE

San Juan 28-6 Unit 127M 30-039-27815 Sec. 20, T28N, R6W Rio Arriba Co., NM

4-1/2" casing report

5/1 to 5/10/05 With 8-3/4" bit drilled ahead. Rotary & slide drilled to 6680'. On 5/10/05 drill pipe became stuck, unable to work free or circ. down. 5/11 to 5/27/05 washed/reamed and fished on pipe. Fished from 5454' – 6680'. 5/27/05 Called & received verbal approval from Adrienne w/BLM to cement plug & sidetrack around fish & continue to drop. 5/27 – 6/3/05 Decided to try and continue fishing. No Luck.

6/3/05 Called BLM & OCD and received verbal approval to abandon hole & side track. 6/3/05 Set cement plug from 5343' – 5643' w109 sx Class H cement w/.5% CaCl2. Displaced w/3.5 bbls FW & 70 bbls mud. Plug in place 6/5/05 @ 0400 hrs. WOC. 6/5/05 Circ. & condition mud @ 4911'. Wash & ream down from 4911' – 5327', bridge @ 5020'. Cement stringers @ 5300'. 6/7/05 With 7-7/8" bit rotary and slide drilled from 5499' – 6330'. 6/8/05 Called BLM & OCD and verified that it was okay to deviate hole – both Ok'd as long as not closer than 10' to section line. Deviation will be required. Drilled ahead to 8011' (TVD). TD reached 6/21/05. Circ. hole.

6/21/05 RIH w/186 its 4-1/2", 11.6#, L-80 casing & set @ 8803' (TMD) with stage collar @ 2689'. RU BJ. Pumped 1st Stage w/preflush of 10 bbls FW/10 bbls mud flush/10 bbls FW. Pumped scavenger of 18 sx (56 cf – 10 bbl slurry) Class C cement. Tailed w/413 sx (818 cf – 146 bbls) Premium Lite. Dropped bomb & displaced w/435 bbls FW w/10# sugar in first 10 bbls & 74 bbls mud. Plug down @ 1719 hrs. Shifted stage collar & displaced 12 bbls to surface. WOC. 2nd Stage – preflushed w/10 bbls FW/ 10 bbls mudflush / 10 bbls FW. Cemented scavenger w/9 sx (27 cf – 5 bbls) Class C cement. Tailed w/150 sx (297 cf – 53 bbl) Premium Lite Class C and displaced w/50 bbls FW & 35 bbls mud. Shift DV tool & displaced w/230 bbls. Circ. 10 bbls to surface. 3rd Stage – pre-flush 10 bbls FW/10 bbls mud flush / 10 bbls FW. Pumped Scavenger cement 9 sx (27 cf – 5 bbls) Class C cement. Tailed w/430 sx (916 cf – 163 bbls) Class C cement. Dropped plug and displaced w/42 bbls FW. Plug bumped @ 0330 hrs 6/22/05. 10 bbls spacer to surface, but no cement. RD cementers. RD & released rig 6/22/05.

Will show casing PT & TOC on next report. PT will be conducted by completion rig.