Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.,

FORM A	PROVE
OMB No.	1004-01
Evnires In	ĥ∕31 100

Lease Serial No.

Contract 3	360
------------	-----

6. If Indian Allottee or Tribe Name

		788	0.3	Jicaring Tribe		
SUBMIT IN TRIPL	ICATE – Other instru	ictions on réverse	side	7. If Vnit or CA/Agreement, Name and/or No.		
1. Type of Well		100	1400 57			
X Oil Well Gas Well	Other			8. Well Name and No.		
2. Name of Operator		V PA.		Bonanza #3		
Elm Ridge Resources, Inc.		CO (500)	ON OFFI	9. API Well No.		
3a. Address		3b. Phone No. (include	area code)	30-043-20497		
PO Box 156 Bloomfield, NM	87413	505-632-3476	,	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T.,		1000 000		W. Lindrtih Gallup Dakota		
790' FNL & 790" FWL	,,,,,			11. County or Parish, State		
Sec. 1-T22N-R3W						
000. 7 722.1 71077				Sandoval, New Mexico		
12. CHECK APPROPRIATE BOX	(ES) TO INDICATE NATU	RE OF NOTICE, REPO	RT, OR OTHER	DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume)		
X Subsequent Report	Casing Repair Change Plans	☐ New Construction☐ Plug and Abandon	Recomplete Temporarily	OtherAbandon		
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Dispo	sal		
Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Elm Ridge Resources moved a rig onto this location. A bridge plug was set above the existing perforated interval. The casing failure was isolated, squeezed, and pressure tested. Prior to drilling out the bridge plug, two Mesa Verde intervals were perforated tested for production potential. No commercial hydrocarbons were found. The perforations were squeeze cemented and pressure tested. The bridge plug was drilled out, and the well will be returned to production by July 2005. The pump jack needs to be replaced.						
k	pamp jack needs to be	торичеч.		PM 3 52 CEIVED MINGTON NM		
14. I hereby certify that the foregoing is	true and correct					
Name (Printel/Typed) Amy	Mackey	Title	Produc	tion Assistant		
Signature My Ma	<u> </u>		Date June 29, 2005			
	THIS SPACE	FOR FEDERAL OR STA	ATE USE			
Approved by		Title		Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its invisidation.						

(Instructions on reverse)

ACCEPTED FOR RECORD

JUL 0 5 2005

NMOCDFARMINGTON FIELD OFFICE