submitted in lieu of Form 3160-5 UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 7005 JUN AM 10 16 Sundry Notices and Reports on Wells Lease Number Jicarilla Contract 108 6.MIN It Indian, All. or Type of Well **Tribe Name** GAS Jicarilla Apache 7. **Unit Agreement Name** 2. Name of Operator CDX RIO, LLC Well Name & Number Jicarilla C #7E Address & Phone No. of Operator 4801 North Butler Avenue, Farmington, New Mexico 87401 (505) 326-3003 API Well No. 30-039-22576 4. Location of Well, Footage, Sec., T, R, M 10. 1700'FSL, 1670'FEL, Sec.13, T-26-N, R-5-W, NMPM Field and Pool Tapacito Gallup/ Basin Dakota 11. **County and State** Rio Arriba Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Action Type of Submission Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection SEE ATTACHED FOR Other Change plans CONDITIONS OF APPROVAL CONDITIONS OF APPROVAL Adhere to previously issued stipulations 13. Describe Proposed or Completed Operations As a follow up and clarification of the sundries filed by CDX RIO, LLC November 1, 2004 and February 2, 2005, the Gallup formation will be completed as detailed in the initial procedure submitted November 1, 2004. The Mesaverde formation will not be completed until the Gallup has been produced with the Dakota for a period of three to six months. Attached is a C-102 plat for the Gallup. CDX RIO, LLC submitted a down hole commingle application to down hole commingle the Mesaverde and Dakota. It was approved as DHC-1708 (CDX RIO, LLC requests this down hole commingle order be changed to reflect the Tapacito Gallup and the Basin Dakota formations. Both formations are pre-approved per Order R-11363. Interest is common. No notification is necessary. MESAVEEDE DHE) TO DHE # 1708a (FOR DAKOTA/TAPACITO GALLAS PHE) 7/12/05 14. I hereby certify that the foregoing is true and correct. Title Agent (This space for Federal or State Office use) APPROVED BY MILL IV Title

CONDITION OF APPROVAL, if any:

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-102 Permit 12585

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number 30-039-22576	Pool Name TAPACITO GALLUP (ASSOCIATED)	Pool Code 58090	
Property Code 33461	Property Name JICARILLA C	Well No. 007E	
OGRID No. 222374	Operator Name CDX RIO, LLC	Elevation 7276	

Surface And Bottom Hole Location

UL or Lot	Section 13	Township 26N	Range 05W	Lot Idn	Feet From 1700	N/S Line S	Feet From 1670	E/W Line E	County Rio Arriba
Dedicated Acres		Joint or	oint or Infill Consol		dation Code		Order 1	No.	

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Electronically Signed By: Mancy Oltmanno
Title: Age T

Date: 6 21-05

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By: Fred Kerr Date of Survey: 11/02/1980

Certificate Number: 3950

Bureau of Land Management Conditions of Approval:

- 1) If cement squeeze work is necessary, contact Matt Halbert of the BLM Farmington Field Office @ (505) 599-6350.
- 2) If this well is located in a Specially Designated Area (SDA), compliance with the appropriate <u>seasonal closure</u> requirements will be necessary.
- 3) Pits must be lined with an impervious material at least 12 mils thick. The pit must be fenced on three (3) sides during workover operations and on the 4th side after the rig moves off location. Pits must be closed within 90 days of completion of the workover operations. Prior to closing the pit the liner must be cut off at mud level.