mitted in lieu of Form 3160-5 UNITED STATES		
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		
Sundry Notices and Reports on Wells		_/
	7005 AUG 9 AM 11 4	3. Lease Number
Type of Well	RECEIVED	NMSF-078138 6. If Indian, All. or
GAS	070 FARMINGTON NN	Table Manage
		7. Unit Agreement Name
Name of Operator	COUNTY DO	Ü
BURLINGTON RESCURCES OIL & GAS COMPANY LP		•
	Alta O	8. Well Name & Number
Address & Phone No. of Operator		Morris #103
PO Box 4289, Farmington, NM 87499 (505) 326-9700	487. On 3	9. API Well No.
Location of Well, Footage, Sec., T, R, M Sec., TN, RW, NMPM	(A) CONTRACTOR	30-045-32834
	C. 62.8215365	10. Field and Pool
		Basin Fruitland Coal
	TTI ATA FINE F	
Unit H (SENE) 1445' FNL & 1130' FEL, Sec. 28, T30N R1		11. County and State San Juan Co., NM
Unit H (SENE) 1445' FNL & 1130' FEL, Sec. 28, T30N R1 CHECK APPROPRIATE BOX TO INDICATE NATURE (San Juan Co., NM
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change	OF NOTICE, REPORT, OTH	San Juan Co., NM
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro	OF NOTICE, REPORT, OTH of Plans enstruction utine Fracturing	San Juan Co., NM HER DATA 4/2
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S	OF NOTICE, REPORT, OTH of Plans enstruction utine Fracturing	San Juan Co., NM HER DATA 4/2
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Final Abandonment Altering Casing Conven	OF NOTICE, REPORT, OTE of Plans enstruction utine Fracturing hut off	San Juan Co., NM HER DATA 4/2
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Final Abandonment Altering Casing Convert	OF NOTICE, REPORT, OTH of Plans astruction atine Fracturing and off aion to Injection	San Juan Co., NM HER DATA 4 / X X Other - V" Casing
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Final Abandonment Altering Casing Convert Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg se	of Plans instruction intine Fracturing inti off ion to Injection 1" bit & tagged cmt @ 137'. 8/ 1 @ 2588'.Pumped preflush of	San Juan Co., NM HER DATA X Other - Casing Color Casing
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Altering Casing Convert Describe Proposed or Completed Operations OS MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg se Cemented w/19sxs(57cu-10bbls) prem lite scavenger cement with the convertion of	of Plans instruction interior fracturing into off ion to Injection 1" bit & tagged cmt @ 137'. 8/ 2 @ 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla	San Juan Co., NM HER DATA X Other - "Casing Color Casing Color Casing
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Final Abandonment Altering Casing Convert Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg se of the Completed Completed W/19sxs(57cu-10bbls) prem lite scavenger cement wented lead w/160sxs(341cu-61bbls) prem lite w/.3% CD32, .25 cu-22bbls) Type 3 cmt w/.25% Cell-o-Flake, 1% CaCl2, .2% F	of Plans instruction intine Fracturing into of Injection To bit & tagged cmt @ 137'. 8/ To 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCN L52. Pumped at rate of 4bbls a	San Juan Co., NM HER DATA X Other - "Casing Color & Ahead to 2590". 10bbls H2O, 10bbls mud, 10bbls ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs minute. Plug down @ 0714hrs
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Altering Casing Convert Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg se Cemented w/19sxs(57cu-10bbls) prem lite scavenger cement wented lead w/160sxs(341cu-61bbls) prem lite w/.3% CD32, .25	of Plans instruction intine Fracturing into of Injection To bit & tagged cmt @ 137'. 8/ To 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCN L52. Pumped at rate of 4bbls a	San Juan Co., NM HER DATA X Other - "Casing Color & Ahead to 2590". 10bbls H2O, 10bbls mud, 10bbls ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs minute. Plug down @ 0714hrs
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Cox Subsequent Report Plugging Non-Roy Casing Repair Water System Final Abandonment Altering Casing Convert C	of Plans instruction intine Fracturing into of Injection To bit & tagged cmt @ 137'. 8/ To 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCN L52. Pumped at rate of 4bbls a	San Juan Co., NM HER DATA X Other - "Casing Color & Ahead to 2590". 10bbls H2O, 10bbls mud, 10bbls ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs minute. Plug down @ 0714hrs
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Final Abandonment Altering Casing Convert Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg se Cemented w/19sxs(57cu-10bbls)prem lite scavenger cement ented lead w/160sxs(341cu-61bbls) prem lite w/.3% CD32, .25 cu-22bbls)Type 3 cmt w/.25% Cell-o-Flake, 1% CaCl2, .2% F lb. Circulated 30bbls of cmt to reserve pit. RD NDBOP. Rig relibe conducted by completing rig. I hereby certify that the foregoing is true and correct.	of Plans instruction itine Fracturing itin to Injection "" bit & tagged cmt @ 137'. 8/ " @ 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCM L52. Pumped at rate of 4bbls a eased 0130hrs. 8/7/05 Will sho	San Juan Co., NM HER DATA X Other— Casing Color & Ahead to 2590' 10bbls H2O, 10bbls mud, 10bbl ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs a minute. Plug down @ 0714hrs ow casing PT on next report. PT
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment Change Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S Final Abandonment Altering Casing Convert Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg se Cemented w/19sxs(57cu-10bbls)prem lite scavenger cement ented lead w/160sxs(341cu-61bbls) prem lite w/.3% CD32, .25 cu-22bbls)Type 3 cmt w/.25% Cell-o-Flake, 1% CaCl2, .2% F lb. Circulated 30bbls of cmt to reserve pit. RD NDBOP. Rig relibe conducted by completing rig. I hereby certify that the foregoing is true and correct.	of Plans instruction itine Fracturing itin to Injection "" bit & tagged cmt @ 137'. 8/ " @ 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCM L52. Pumped at rate of 4bbls a eased 0130hrs. 8/7/05 Will sho	San Juan Co., NM HER DATA X Other - "Casing Color & Ahead to 2590". 10bbls H2O, 10bbls mud, 10bbls ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs minute. Plug down @ 0714hrs
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Notice of Intent Abandonment New Co Recompletion Non-Ro Casing Repair Water S Final Abandonment Altering Casing Convert Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg seg. Cemented w/19sxs(57cu-10bbls) prem lite scavenger cement wented lead w/160sxs(341cu-61bbls) prem lite w/.3% CD32, .25 cu-22bbls) Type 3 cmt w/.25% Cell-o-Flake, 1% CaCl2, .2% F05. Circulated 30bbls of cmt to reserve pit. RD NDBOP. Rig reliber conducted by completing rig. I hereby certify that the foregoing is true and correct. Amanda Sandon	of Plans instruction itine Fracturing itin to Injection "" bit & tagged cmt @ 137'. 8/ " @ 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCM L52. Pumped at rate of 4bbls a eased 0130hrs. 8/7/05 Will sho	San Juan Co., NM HER DATA X Other— Casing Color & Ahead to 2590' 10bbls H2O, 10bbls mud, 10bbl ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs a minute. Plug down @ 0714hrs ow casing PT on next report. PT
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission	of Plans instruction itine Fracturing itin to Injection "" bit & tagged cmt @ 137'. 8/ " @ 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCM L52. Pumped at rate of 4bbls a eased 0130hrs. 8/7/05 Will sho	San Juan Co., NM HER DATA X Other— Casing Color & Ahead to 2590' 10bbls H2O, 10bbls mud, 10bbl ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs a minute. Plug down @ 0714hrs ow casing PT on next report. PT
CHECK APPROPRIATE BOX TO INDICATE NATURE (Type of Submission Type of Action Abandonment Change Recompletion New Cox Plugging Non-Ro Casing Repair Water Symbol Prinal Abandonment Altering Casing Converted Proposed or Completed Operations Describe Proposed or Completed Operations O5 MIRU Bearcat #4. PT casing @600# 30 min ok. RIH w/6 1/4 ulate hole. 8/6/05 RIH w/60 jts of 4 ½" 10.5# J55 ST&C csg seg. Cemented w/19sxs(57cu-10bbls) prem lite scavenger cement wented lead w/160sxs(341cu-61bbls) prem lite w/.3% CD32, .25 cu-22bbls) Type 3 cmt w/.25% Cell-o-Flake, 1% CaCl2, .2% F05. Circulated 30bbls of cmt to reserve pit. RD NDBOP. Rig reliberation of the conducted by completing rig. I hereby certify that the foregoing is true and correct. ed Amanda Sandon Space for Federal or State Office use)	of Plans instruction intine Fracturing into off ion to Injection "bit & tagged cmt @ 137'. 8/ @ 2588'.Pumped preflush of v/.3% CD32, .25pps Cell-o-Fla pps Cell-o-Flake, 6.25pps LCN L52. Pumped at rate of 4bbls a leased 0130hrs. 8/7/05 Will sho	San Juan Co., NM HER DATA X Other— "Casing 10bbls H2O, 10bbls mud, 10bbl ake, 6.25pps LCM1, 1% FL52. M1, 1% FL52. Tail in w/90sxs a minute. Plug down @ 0714hrs ow casing PT on next report. PT accepted For REC Accepted For REC