RECEIVED

Form 3160-5 (August 2007)

UNITED STATES NOV 28 2012 UNITED STATES WHO STATES WHO

BUREAU OF LAND MANAGEMENT

Farmington Field Office Bureau of Land Manageme.

OMB No. 1004-0137 Expires: July 31, 2010

6. If Indian, Allottee or Tribe Name

5. Lease Serial No.

NMSF-043260-A

FORM APPROVED

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
showdowed well. Her France 2460 2 (ADD) for such means ale

	well. Use Form 3160-3 (A				
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Sas Well Other				8. Well Name and No. Murphy E 5	
2. Name of Operator				9. API Well No.	
Burlington Resources Oil & Gas Company LP				30-045-26476	
3a. Address		3b. Phone No. (include area co	ode)	10. Field and Pool or Exploratory Area	
PO Box 4289, Farmington, NM 87499 (505) 326-9700			כ	Aztec Pictured Cliffs	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Parish, State		
Surface Unit I (NESE), 1590' FSL & 1070' FEL, Sec. 33, T30N, R11W			San Juan ,	New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR C					R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	R	Reclamation	Well Integrity
X Subsequent Report	Casing Repair	New Construction	\square R	Recomplete	Other .
	Change Plans	X Plug and Abandon	T	emporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	v	Vater Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

10/26/12 Notified Brandon Powell/OCD (J.Hagstrom/BLM onsite) of tbg stuck. Free to 2265', tag up @ 2270', end of tbg @ 2296'. Requested permission to leave in & set 1st plug @ 2178'. Verbal approval rec'vd.

10/29/12 Notified Brandon Powell/OCD (J.Hagstrom/BLM onsite) of plug change. TOC @ 100' per 1985 temp survey. Cmt is covering shoe, surface pipe @ 146'. Requested permission to combine plugs 2&3, fill up from inside @ 1031', fill to surface & cut off @ 1". Verbal approval rec'vd.

DOIN DEAG 140

The subject well was P&A'd on 10/30/12 per the above no	tifications and attached report.	OIL CONS. DIV. DIST. 3		
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Dollie L. Busse	Title Staff Regulatory Technician			
Signature Million Cause	Date 11/27/12			
THIS SPACE FOR FEDE	RAL OR STATE OFFICE USE	AGRETIED FOR RECORD		
Approved by	Title	MOV 8 0 2012		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or c that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.	ertify	AMMINITON FIELD OFFICE		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any perfalse, fictitious or fraudulent statements or representations as to any matter within its juris		rtment or agency of the United States any		

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources **Murphy E 5**

October 31, 2012 Page 1 of 2

1590' FSL and 1070' FEL, Section 33, T-30-N, R-11-W San Juan County, NM Lease Number: NMSF-043260A API #30-045-26476

Plug and Abandonment Report Notified BLM and NMOCD on 10/23/12

Plug and Abandonment Summary:

- Plug #1 with 24 sxs (28.32 cf) Class B cement inside casing from 2173' to 1302' to cover the Fruitland Coal and Pictured Cliffs top.
- Plug #1a with 16 sxs (64.9 cf) Class B cement circulate 16 sxs out as per BLM rep. Redo Plug #1 with 16 sxs (18.88 cf) inside casing from 1654' to 1074'.
- Plug #2 with 32 sxs (37.76 cf) Class B cement inside casing from 1054' to surface, circulate good cement.
- Plug #3 with 65 sxs Class B cement found cement 44' down in 2-7/8" casing and 63' in annulus install P&A marker.

Plugging Work Details:

- 10/25/12 Rode rig and equipment to location. Open up well; no pressures. Advance Safety checked for H2S. No H2S. Pumped 4.25 bbls locked up at 800 PSI. Calculated tubing distraction at 2200'. PU 1-1/4 slips from wellhead strip in 2-7/8" wellhead flange. NU BOP and function test. RU to 8-5/8" bradenhead. Pressure test bradenhead 3.5 bpm at 250 PSI. Circulated cement down 8-5/8" establish TOC at 73'. Latched on to 1-1/4" tubing and worked pipe pulling 15K over string weight. Stuck pipe. BLM, NMOCD and COPC notified. SI well. SDFD.
- 10/26/12 Open up well; no pressures. PU 1" free point tool. RIH tag at 2270'. Found 1-1/4 tubing free at 2265', (tubing landed at 2296', PC perfs 2228' to 2307'). POH and LD free point tool. Wait on orders. PU 1: jet cutter tool, RIH to 2265' and jet cut 1-1/4 tubing. POH. TOH and tally 1-1/4 tubing, 69 joint, 1-4' cut joint. RU Bluejet Wireline. PU gauge ring RIH to 2190'. PU 2-7/8" CIBP, RIH and set at 2178'. Did not set, tagged CIBP at 2264'. POH. Wait on Hot Shot for 2-7/8" CIBP. PU 2-7/8" CIBP and RIH and set at 2178', PUH and stacked out on plug, good tag. POH. LD setting tool. SI well. SDFD.
- 10/29/12 Open up well; no pressures. TIH with 34 stands and tag 2-7/8 CIBP at 2178'. LD 2 joints. Circulate well clean. Pressure test 2 times, small leak off about 100 PSI in a minute. RU Bluejet wireline. Ran CBL from 2178' to 200' (casing had to many air bubbles at 200 PSI). PU 1-4' plugging sub, TIH with 33 stands 1-1/4 IJ tubing. PU 1-8' sub tag 2-7/8 CIBP at 2173'. Spot plug #1 with TOC at 1302'. SI well. SDFD.
- 10/30/12 Open up well; no pressures. TIH with 12 stands. PU 12 joints tag with 8' stick up to 1654'. Attempt pressure test 3x, 1-1/4 pipe rams leaking. POH. Tag top of cement low at 1654'. Spot plug #1a with TOC at 1074. Spot plug #2 with TOC at surface. ND BOP. Dig out wellhead. Issue Hot Work Permit. Cut off wellhead. Found cement down in 2-7/8" casing 44' and 63' in annulus. Spot plug #3 and install P&A marker.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources **Murphy E 5**

October 31, 2012 Page 2 of 2

10/31/12 Travel to location. RD & MOL.

John Hangstrom, BLM representative, was on location. Robert Trujillo, COPC representative, was on location.

ConocoPhillips

Schematic - Current

MURPHY E #5

District Field Name API / UWI County State/Province NORTH HBR_SAN JUAN 3004526476 SAN JUAN **NEW MEXICO** Original Spud Date Surface Legal Location East/West Distance (ft) East/West Reference North/South Distance (ft) North/South Reference 8/2/1985 SEC:33;TWN:030N;RN.. 0.00 0.00

