Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMNM2337

SUNDRY	NOTICES AND I	REPORTS ON	4 WELLS
Do not use th	ia faim far arana	cala ta drill ar	to ro ontor o

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

				i i				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ment, Name and/or No.		
1. Type of Well Gas Well Gother					8. Well Name and No. CHACO 3			
Name of Operator     Contact: ALIPH REENA     DUGAN PRODUCTION CORPORATION Aliph.reena@duganproduction.com					9. API Well No. 30-045-22472-0	0-S1		
3a. Address	**************************************	3b. Phone N Ph: 505-3	o. (include area cod	e)	10. Field and Pool, or Exploratory			
FARMINGTON, NM 87499	·		25-1021		WILDCAT			
4. Location of Well (Footage, Sec., 7 Sec 1 T24N R9W SENW 170 36.345810 N Lat, 107.744247	n)			11. County or Parish, a				
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATI	E NATURE OF	NOTICE, RE	PORT, OR OTHER	RDATA		
TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	☐ Acidize	□ Dec	pen	Producti	on (Start/Resume)	☐ Water Shut-Off		
, —	☐ Alter Casing	□ Fra	cture Treat	□ Reclama	tion	☐ Well Integrity		
Subsequent Report	Casing Repair	□ Nev	v Construction	Recompl	ete	Other		
Final Abandonment Notice	Change Plans	🗷 Plu	g and Abandon	☐ Tempora	rily Abandon			
6/	Convert to Injection	□ Plu	g Back	□ Water Di	☐ Water Disposal			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandoniment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Dugan Production Corp. requests permission to plug the well as per the following procedure:  1) Set CR @ 5088'. Set plug above the retainer from 5088'-4988' inside casing with 12 sks Class B neat cement (14.2 cu ft).  2) Spot Mancos plug from 4333'-4433' inside casing with 12 sks Class B neat cement (14.2 cu ft).  3) Set CR @ 1740'. Spot Pictured Cliffs plug from 1690'-1790' inside casing with 12 sks Class B neat cement (14.2 cu ft).  4) Set CR @ 1535'. Spot Fruitland Coal plug from 1485'=1585' inside casing with 12 sks Class B neat cement (14.2 cu ft).  5) Set CR @ 1063'. Spot Ojo Alamo-Kirtland plug from 850'=1713' inside casing with 28 sks Class B neat cement (23-5 cu ft).  6) Perforate @ 280'. Set surface plug from 280' to surface. Tag TOC @ surface.  Set CR within 50' of top Callup perfs fextend Mancos plug down to 4704'								
14. Thereby certify that the foregoing is true and correct.  Electronic Submission #162360 verified by the BLM Well Information System  For DUGAN PRODUCTION CORPORATION, sent to the Farmington  Committed to AFMSS for processing by STEVE MASON on 12/13/2012 (13SXM0373SE)								
Name (Printed/Typed) ALIPH RE	ENA		Title PROD	UCTION ENG	NEER			
Signature (Electronic S	ubmission)		Date 12/11/2	2012				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US				
Approved By STEPHEN MASON  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Farming			Date 12/13/2012		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	tatements or representations as	to any matter w	ithin its jurisdiction	na winiuny to mal	ce to any department or a	agency of the Onited		


# Additional data for EC transaction #162360 that would not fit on the form

- 32. Additional remarks, continued
- 7) Cut wellhead and install dry hole marker.

#### P & A Schematic

Chaco # 003, Dakota 300-45-22472 1700 FNL 1450 FWL F S1 T24N R9W

289/11.127(118)= 215m 58/43899(148)= 10 55 230/4.04 (1-18)= 48 50 79 545



8 5/8" J-55 24# casing @ 230'

Perforate @ 280'. Spot plug from 280' to surface. Tag TOC @ surface.

Calculated TOC @ 496' from surface

Set-GR-@-1063'. Spot inside plug w/ 26 sks Class B neat (23:6 cu.ft) (850'-1113). [Ojo Alamo, Kirtland Plug]

1206-844 50/ 11.167 (1.18)= 31 54

CR-@-1535'. Spot inside plug w/ 12 sks Class B neat (14.2 cu.ft)( 1485'-1585'). [Fruitland Coal]

GR.@ 1740'. Set plug w/ 12 sks (14.2 cu.ft) Class B neat cement. (1690'-1790'). [Pictured Cliffs]

CR-@-3285'. Set plug w/ 12 sks (14.2 cu.ft) Class B neat cement. (3235' 3335'). [Mesaverde] 2600 2500

Spot inside plug w/ 12 sks Class B cement (14.2 cu.ft). (4333'-4433'). [Mancos]. DV Tool @ 4385'

12 (11.167)(1-18) = 158.

CR @ 5088'. Set Inside Plug with 12 sks (14.2 cu.ft) Class B. (4988'-5088').

Gallup Perforated @ 5188' - 6168'

4  $\frac{1}{2}$ " 9.5/11.6 # casing @ 6379' RKB.

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 3 Chaco

### **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Measverde plug from 2600' 2500'.
- b) Place the Fruitland plug from 1509' 1409'.
- c) Place the Kirtland/Ojo Alamo plug from 1206' 844'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

Form 9-331 (May 1963)		JNITED STATES	SUBMIT IN TRIPLICAT	
* . ·		MENT OF THE IN	IERIOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	G	EOLOGICAL SURVE	<u> </u>	NM 2337
	SUNDRY NOT	CES AND REPOR	TS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
			plug back to a different reservoir, such proposals.)	
<u>.</u>	Use AFFLICA	TION FOR PERSITT— 10F	such proposals.)	7. UNIT AGRESMENT NAME 12 3 3
والد [	WELL OTHER			
2. NAME OF OPER				8. FARM OR LEASE NAME
Dugan P	roduction Corp	•	•	Chaco gg gg Again
3. ADDRESS OF O	PERATOR			9. WELL NOW 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Box 234	, Farmington,	NM 87401	·	3 WELL NOT STORY 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4. LOCATION OF W See also space At surface	VELL (Report location cl > 17 below.)	early and in accordance wi	th any State requirements.*	10. FIELD-AND-POOL, OR WILDCAT S
De bulluto				J. SEC., T., R., M., OR BLK, AND
	1700' FNL	- 1450' FWL		BURYAY OR ARWAY
				Sec. 12.724N, R9W
14. PERMIT NO.		15. ELEVATIONS (Show whe	ther DP, RT, GR, etc.)	12. COUNTY OF PARISH 13- STATE
			6583' GR	San Juan NM
16.	Charle An	proprinta Box To India	ate Nature of Notice, Report, o	Other Deta Table
			• • •	
	NOTICE OF INTEN	104 40:	יפטא.	SEQUENT REPORT OF 1
TEST WATER	SHUT-OFF	ULL OR ALTER CASING	WATER SHUT-OFF	SREPAIRING WELL
FRACTURE TR	<u>[</u> ]	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR AC	[[	BANDON*	shooting or acidizing  (Other) Run CSG	DABANDONMEST.
REPAIR WELL (Other)	, [_] ,	HANGE PLANS	(Note: Report res	ults of multiple completion on Well
	OSED OR COMPLETED OPE	RATIONS (Clearly state all p		empletion Report and Log form.) - 7
proposed w nent to this	ork. If well is direction	nally drilled, give subsurfac	e locations and measured and true ve	rtical depths for all-markers and zones perti-
	•			S
3-7-78	TD 6400'	. Ran IES and C	DL logs by GO Wireline	(had to make 3 attempts
	to get 1	ogging tool on b	ottom). Going in hole	to lay down drill
	pipe.			
•			•	
3-8-78	Ran 209 jts	4-1/2" OD 10.5#	K-55 8R ST&C CF&I csg	set @6379' RKB.
	Halliburton	cemented first s	tage with 375/sx Class	"B" 4% gel,
			l slury 580 cu ft. Ra	
	POB 4:50 p.m		mud returns while cem	enting.
		tool, circulate	ed hole 3 hrs.	The state of the s
			aker Stage Tool at 438	51 with 450
	65-35-12 w/1	/4# flo cele per	sx followed by 50 sx	class "B" neat
• .	2/1/4/# flo	cele per sx. To	tal slury 1180 cu ft.	Preflushed
•	hole w/500 g	als mud flush.	Good circulation throu	ghout job 23 1997
	closed stage	tool w/2500 psi	Maximum cementing p	ress. 600 psi.
(.	Slight show	of cement to sur	Maximum cementing p face. Job complete 8:5	Preflushed shout job. MARCA 1970 p.m. 3-7-18011
•				
	$\cap$	·		A the following
18. I hereby certi	ity that the foregoing is	true and correct		
signed	J.H. WILLAND	more r	Petroleum Engineer	paris = 3-115-78 1 1
	Thomas A. Dug	an	,	<b>VALUE 1 1 1 1 1 1 1 1 1 1</b>
f space fdT)	or Federal or State offi	e use)		one on the property of the pro
APPROVED I	BY	TITLE	3	EARSES SEE SEE
	OF APPROVAL, IF A	NY:	* C	1000 1000 1000 1000 1000 1000 1000 100