Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

JAI	N	0	7	20	17

Final Abandonment Notice

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Convert to Injection

5. Lease Serial No.	
SF-078883	
5. If Indian, Allottee or Tribe Name	

abandoned	well. Use Form 3160-3 (A				
SL	IBMIT IN TRIPLICATE - Other ins	7. If Unit of CA/Agreement, N	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well			Can	yon Largo Unit	
Oil Well	X Gas Well Other	8. Well Name and No. Canyon Largo Unit 485E			
2. Name of Operator			9. API Well No.		
Burling	ton Resources Oil & Gas	30-0	30-039-31060		
3a. Address 3b		3b. Phone No. (include area code)	10. Field and Pool or Explora	tory Area	
PO Box 4289, Farmington, NM 87499 (505) 326-9700			Basin Mancos/Basin Dakota		
4. Location of Well (Footage, Sec., T., Surface UNIT J (N	R.,M., or Survey Description) NWSE), 2515' FSL & 1890'	FEL, Sec. 8, T25N, R6W	11. Country or Parish, State Rio Arriba	, New Mexico	
12. CHECK T	HE APPROPRIATE BOX(ES) TO INDICATE NATURE OF	NOTICE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION-	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation .	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	X Other Remove CIBP	
- O.P.	Change Plans	Plug and Abandon	Temporarily Abandon	& DHC	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug Back

Water Disposal

12/13/12 MIRU DWS 26. NDWH. NU BOPE. PT BOPE. TEST OK. TOOH w/ 2 3/8" tubing. DO CIBP @ 6,920'. **12/15/12** TIH, tag PBTD @ 7,324'. Circulate clean. Flow well.

12/21/12 RU WL. Run Completion Profile Log from 6,020' - 7,300'. RD WL. TIH w/ 230 jts., 2 3/8", 4.7#, J-55 tbg., set @ 7,091' (new setting depth). PT tubing, test OK. ND BOPE. NU WH. RD RR @ 12:00 hrs on 12/22/12.

This well is now a Basin Mancos/Basin Dakota well being commingled per DHC Order #4528

RCVD JAN 11'13 DIL CONS. DIV. DIST. 3

-			
Title	REGULATORY TECHNICIAN 1/5/2013		
· Date			
ERAL OR	STATE OFFICE USE	AGREPTED FOR RECORD	
		JAN 0 9 2013	
	Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			
	DERAL OR	Date DERAL OR STATE OFFICE USE Title or certify	