

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: Lloyd B 600	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner BLM (SF-078161)	API No. 30-045-27181
--------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter L	Section 1	Township 29N	Range 11W	Feet from the 1450	North/South Line South	Feet from the 1085	East/West Line West	County San Juan
-------------------------	---------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.75131 Longitude 107.9477

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 bbls	Volume Recovered
Source of Release Produced Water Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1/21/2013 at 10:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD JAN 25 '13 OIL CONS. DIV.	
By Whom?	Date and Hour DIST. 3	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Approximately 5bbls of produced water overflowed from the Produced Water Tank. No amount was recovered. The release did not leave the location and is contained within the berm. The well is currently shut-in.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: <u>1/29/2013</u>	Expiration Date:
E-mail Address: <u>crystal.tafoya@conocophillips.com</u>		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>1/23/2013</u> Phone: <u>(505) 326-9837</u>			

* Attach Additional Sheets If Necessary

nJK 1302947926