

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 32-8 Unit 262	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner BLM (SF-079013)	API No. 30-045-30989
--------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	17	32N	8W	1768	North	1978	East	San Juan

Latitude 36.98656 Longitude 107.69551

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 82 bbls	Volume Recovered 80 bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery 1/17/2013 at 1:36pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM (Mark Kelly) & OCD (Jonathan Kelly)	
By Whom? Crystal Tafoya	Date and Hour 1/17/2013 at 5:50pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



**RCVD JAN 23 '13
OIL CONS. DIV.
DIST. 3**

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Y-strainer on transfer pump froze and broke allowing 82bbls of produced water from the pipeline to backflow into the location. The release remained on location and was contained within the berm. Water trucks were able to recover 80bbls of produced water. The well was immediately shut-in and is waiting to be repaired.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 3/07/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/22/2013 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

nJR 1306642891