Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FEB 22 201

1. Sami Colombia Windows

FORM APPROVED 1, 2014

)	OMB No. 1004-0
	Expires: October 3
5. Lease Serial No. NM 05948	
NM"05948	

Do not use this fo	OTICES AND REPO orm for proposals t Jse Form 3160-3 (A	o drill or to re-	enter an	6. If Indian, Allottee or	Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. CA NMNM 9426		
I. Type of Well ☐ Oil Well ☐ Oas Well ☐ Other				8. Well Name and No. Freeman #11-3		
2. Name of Operator Four Star Gas & Oil Company			9. API Well No. 30-045-28872			
Ga. Address ATTN: Regulatory Specialist 332 Road 3100 Aztec New Mexico 87410 350 Phone No. 370 Security Specialist Support Su			de area code)	10. Field and Pool or Exploratory Area 71629		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. County or Parish, State		
1780 FNL 865 FEL H-11-31N-13W				San Juan County, New Mexico		
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICAT	E NATURE OF NOT	ICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION			TYPE OF AC	TION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Tro	at Rec	duction (Start/Resume)	Water Shut-Off Well Integrity Other HIT repair	
Subsequent Report	Casing Repair Change Plans	☐ New Consti		complete mporarily Abandon	Other HII repair	
Final Abandonment Notice	Convert to Injection	Plug Back	_	ter Disposal		
following completion of the involv testing has been completed. Final adetermined that the site is ready for 2/7/2013 MIRU and POOH with rod 2/8/2013 Changed out hold down pRU cap string equipment to POOH. 2/11/2013 PU and RIH with tubing the POOH with production tubing and NPU bit, bit sub, string float, and 2 3/8 POOH to 1773 FT to get above the 2/12/2013 RIH with tubing and tagg POOH and LD Bit, Bit sub, and string 2/13/2013 Finish RIH with tubing ar ND BOPs and NU well head tested RIH with pump and rods, Set pump RD, prepare to move on the freeze. See attached wellbore diagram.	Abandonment Notices must final inspection.) s. ins on well head. POOH with tubing and ca agged at 2074 FT. ipple, sand screen, pup, our tubing RIH tagged at 20 slotted liner, going to RIH ed at 2070 FT, RU lines to g float. PU and RIH with the cap string, landed EOT word to 1500 PSI held-5 medical inspection.	be filed only after all a up string, pulled 13 journey dump valve. LD BHA 074 FT. Broke circul in the morning and in clean out. Cleaned mule shoe, seat nipp at 2049.61 FT, Sea nin-good test	ints. High winds-shows and loaded tubing ation-unloaded well ag for fill. SWIFN. I out from 2070 to 201e, and 50 joints, Stripple at 2029.19	g reclamation, have been ut down. SWIFN onto tubing float., cleaned out to 2080 F 080 FT. Circulated cleawIFN. FT. Landed hanger.	completed and the operator has	
 1 hereby certify that the foregoing is to 	ue and correct. Name (Printe	ed/Typed)				
April E. Pohl		Title	Regulatory Specia	alist		
Signature April E	Pohl	Date	2/22/1	13		
	THIS SPACE	FOR FEDERAL	OR STATE OF	FICE USE	ACCEPTED FOR RECOR	
Approved by Conditions of approval, if any, are attached	Approval of this notice doe	s not warrant or certify	Title	E	Date [17] 0 1 2013	
hat the applicant holds legal or equitable t ntitle the applicant to conduct operations	tle to those rights in the subje		Office		VACIONALIA VA	

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,



Wellbore Schematic

