submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

		200E C	בח הה			
		<del>ਦਾਹਰ ਨ</del>	EP 26	PM 1	485.	<b>Lease Number</b> BIA #14-20-603-2022
1. T	ype of Well		RECE	IVED	6.	If Indian, All. or
0	il Well	070	FARMI	NGTON .	NM	Tribe Name Navajo
·					7.	Unit Agreement Name
2. N	ame of Operator					Horseshoe Gallup
	laya Minerals & Energy, c/o NMOCD Aztec District	Office				· · · · · · · · · · · · · · · · · · ·
					8.	Well Name & Number
3. A	ddress & Phone No. of Operator					HSGU #86
	1000 Rio Brazos Road, Aztec, NM 87410 505-334-61	78			9.	API Well No.
						30-045-10651
4. L	ocation of Well, Footage, Sec., T, R, M				10.	Field and Pool
-	'88' FNL and 1869' FWL, Section 24, T-31-N, R-17-W				11.	Horseshoe Gallup County & State
	00 11NL and 1005 FWL, Section 24, 1-31-N, K-17-W				11.	San Juan County, NM
						36 27 20 30
12. C	HECK APPROPRIATE BOX TO INDICATE NATURE	OF NOT	ICE. RE	PORT. O	THER (	DATA
	ype of Submission Type of Action		•			
	Notice of Intent X Abandonment	(	Change of	of Plans		SEP 200 S
	Recompletion			struction		OIL SONS ON SONS
	X Subsequent Report Plugging Back			itine Frac	turing	
	Casing Repair		Water S		4.	OIL OIST. SOIV. ON
	Final Abandonment Altering Casing	· <del></del>	Convers	ión to Inje	ection	
	Other -					\$ \$ 10 mm 10 600
13 D	escribe Proposed or Completed Operations		<del></del>			CL CL CL CL
.0. 2	A-Plus Well Service Plugged and Abandoned	the abo	ve well	NMSA 1	1978 S	Section 13-1-127
	Purchase Agreement: 415210700028; Purchase					7001.017 10 1 127,
	, a.o., a.o., ig. oo., io., ii , io., io. oo., i a.o., a.					
8/11/0	D5 MOL and RU rig. Check well pressures: 40# on o	casing. 0	)# on BH	. 0# on tu	ıbina. E	Blow well down. TOH and
	LD 2 - 3/4" rods. PU polish rod and hang off. Shut	_		,		
8/12/	· · · · · · · · · · · · · · · · · · ·		D 53 - 3	/4" rods.	ND wel	lhead. NU BOP and test.
<b>4 –</b> .	TOH and LD 44 joints 2.875" tubing. Shut in well.					
8/15/	•		4'. TIH a	nd set 5.	5" CR a	at 1232'. Sting out of CR.
	Circulate casing clean with 30 bbls of water. Pre					
	below CR, then sting out. Plug #1 with CR at 12			•	•	•
	1232' to 969' to cover the Gallup interval. TOH and LD tubing. Perforate 2 holes at 164'. Establish					
	circulation out bradenhead to surface. Note: had			-		
	hours to circulate BH annulus clean. Plug #2 v	-				
	casing from 164' to surface, circulate good ceme				•	
	Dig out and cut off wellhead. Found cement at the					
	sxs cement install P&A marker. RD and MOL.	o surrace	J III DOUI	uic 5.5 (	ousnig a	and in the drinding. With 10
	H. Villanueva, NMOCD and G. Shay, Navajo BLM	l were o	n locatio	n		
	11. Villandeva, Nivicob and C. Shay, Nevajo beliv	i, Weie O	ii locatio	11.		
SIGN	ATURE Walkin Hear Con	tractor		Septem	hor 7 2	005
SIGN	William F. Clark	liacioi		Septem	DEI 1, Z	.003
/Th:-					AÙ	
( I NIS	space for Federal or State Office use)					CED 2 7 200E
ДРР	ROVED BY Title					SEP 2 7 2005 Date
	DITION OF APPROVAL, if any:				C:35	- Date
55.1	and the state of t					···· Com