

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

5. Lease Serial No.

SF-080711

AUG 07 2013

6. If Indian, Allottee or Tribe Name

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

Bureau of Land Management

7. Unit of Government Name and/or No.

San Juan 30-6 Unit

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

8. Well Name and No.

San Juan 30-6 Unit 457S

2. Name of Operator

Burlington Resources Oil & Gas Company LP

9. API Well No.

30-039-27694

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

10. Field and Pool or Exploratory Area

Basin Fruitland Coal

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface UNIT F (SENW), 1340' FNL & 2340' FWL, Sec. 19, T30N, R6W

11. Country or Parish, State

Rio Arriba, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water Shut-Off

☒ Subsequent Report

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☐ Recomplete

☒ Other TA Sundry

☐ Final Abandonment Notice

☐ Convert to Injection

☐ Plug Back

☒ Temporarily Abandon

☐ Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

8/2/13 - MIRU AWS 748. ND WH. NU BOPE. PT BOPE. Test OK. TOOH w/ 2 3/8" tubing. RU Blue Jet, TIH w/ 7" CBP and set at 3,340'. ND BOPE. NU WH.

8/5/13 - RU High Tech. Conduct MIT on 7" Csg w/ 600# for 30 min. Test OK. NMOCD Present - charted-witnessed by Paul Wiebe. MIT chart is attached. RD RR @ 16:30 hrs on 8/5/13.

RCVD AUG 9 '13  
OIL CONS. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

DENISE JOURNEY

Regulatory Technician

Title

Signature

Denise Journey

Date

8/7/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

AUG 08 2013

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 181  
false, fict  
(Instruct)

NMOCD T/A EXPIRES 8-5-18  
FEDERAL EXPIRATION MAY VARY  
CONTACT BLM FOR FEDERAL  
EXPIRATION DATE

a crime for any person knowingly and willfully to make to any department or agency of the United States any  
ter within its jurisdiction.

NMOCD

dib




CHART NO. MC MP-1000-1HR  
METER 812/13

CHART PUT ON  
6-5-2013

LOCATION

REMARKS

TAKEN OFF  
AW 5.798 M

53-30-6 #4225  
High Tech Rentals  
by Homer

6-5-2013

1/23 Paul White 6-5-2013

CASTING

54.8