

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Transwestern Pipeline Co.	Contact Charlie Allen
Address P.O. Box 1019 Thoreau NM 87323	Telephone No. W: 505-862-7443 C: 505-870-9432
Facility Name Thoreau Comp. Station 5	Facility Type Natural Gas Comp. Station

Surface Owner Transwestern Pipeline Co.	Mineral Owner Transwestern Pipeline Co.	Lease No.
---	---	-----------

LOCATION OF RELEASE

Unit Letter	Section 20	Township 14-N	Range 13-W	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	--------

Latitude N 35-25'-31" Longitude W 108-14'-09"

~~36.4152773~~ ~~-108.2358333~~
NATURE OF RELEASE

Type of Release: Natural gas release into the atmosphere	Volume of Release: 2519 MCF	Volume Recovered: none
Source of Release: Blow down stack and ESD stack in station yard	Date and Hour of Occurrence 7/17/13 07:27	Date and Hour of Discovery 7/17/13 07:27
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell at OCD Aztec Office 1-505-334-6178 Ext.15 Cell 1-505-320-0200	
By Whom? Charlie Allen	Date and Hour 7/17/13 around 13:00 PM Left message on office phone.	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

RCVD AUG 23 '13
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

TRANSWESTERN PIPELINE'S THOREAU COMPRESSOR STATION 5 DID AN ANNUAL ESD (EMERGENCY SHUT DOWN) IT SHUT IN THE SUCTION AND DISCHARGE STATION FIRE GATE VALVES AND VENTED ALL GAS INTO THE ATMOSPHERE. THERE WAS NO REMEDIAL ACTION NEEDED BECAUSE ALL GAS WAS RELEASED INTO THE ATMOSPHERE.

Describe Area Affected and Cleanup Action Taken.*

TRANSWESTERN PIPELINE THOREAU COMPRESSOR STATION 5 YARD. THERE WAS NO CLEANUP ACTION TAKEN DUE TO THE GAS BEING RELEASED INTO THE ATMOSPHERE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Charlie Allen	Approved by District Supervisor: 	
Title: Operations Leader	Approval Date: 9/11/2013	Expiration Date:
E-mail Address: charlie.allen@energytransfer.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/22/13 Phone: W: 505-905-7443 C: 505-870-9432		

* Attach Additional Sheets If Necessary

NSK1325441733