Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

Jicarilla Contact 287

6. If Indian Allottee or Tribe Name

Jiçarilla Apache Tribe

	. ,			Jilyan IIIa Apa		
		illy out 40	111 6 00	7. If Unit or C	A/Agreement, Name an	d/or N
SUBMIT IN TRIPLICATE – Other instructions on reverse side				0	MILL 6	54262728
				1 7. C 20	1 7 5	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
1. Type of Well 070 FARMINGTON NI				8. Well Name	27172	-3c^ A
X Oil Well Gas Well Other						F 364 20
2. Name of Operator				EPCMU #4	, , ,	
Benson-Montin-Greer Drilling Corp.				9. API Well N	[02	Dia v
3a. Address 3b		Phone No. (include area code)		30-039-82269		
4900 College Blvd., Farming	5-325-8874		10. Field and Pool, or Exploration Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				East Puerto Chiquito Mancos C		
SEC. 21-T27N-R1E				11. County or Parish, State		
660' FSL & 1920' FEL				Die Amilee New Marries		
				Rio Arriba, New Mexico		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION				W.	
		1 5	D. Bornellon	(01		
Notice of Intent	Acidize	Deepen		(Start/Resume)	Water Shut-Off	:
Cubecount Remont	Alter Casing	Fracture Treat	Reclamatio Recomplete		Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction	Temporaril		Other	
Final Abandonment Notice	Convert to Injection	Plug and Abandon Plug Back	Water Disp			
13. Describe Proposed or Completed Operation					<u> </u>	
Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) MIRU Llaves Well Service. NU BOP. RIH with 4-3/4 bit, bit sub, 31-jts 2-3/8" tubing - tag fill @ 857'. Set PS - drilled to joint #43 - lost circulation. POH with 8-stds. Drilled to joint #48 - lost circulation - mix mud. Drilled to joint #57 @ 1785'. RIH to joint #60 @ 1878' - lost circulation- mixed mud. Hard to drill. Drilled to joint #62 @ 1940' - called BLM (Jim) was told to plug well from 1940' to surface. POH with work string. TIH with 62-jts @ 1940' - pump 72 sks cement from 1940' to 1258'. TOC @ 1258'. POH with 22-jts - bottom of tubing @ 1258'. Pump 63 sks cement from 1258' to 676'. POH with 20-jts - bottom of tubing @ 645'. Circulate hole clean with water. POH with rest of work string. RU wireline and perf squeeze holes @ 269' - could not break circulation to surface. Pump 30 bbls water. Talked with BLM was told to perf. squeeze hole @ 50'. Pump clean water - good circulation. Clean outside 5-1/2" casing with 10 bbls water. Pump cement down 5-1/2" casing into squeeze holes. Circulate to surface. Cut off wellhead.						
14. I hereby certify that the foregoing	is true and correct		-	-		
Name (Printed/Typed) Trudy Grubolnik			Dec. of the section	on Toch=!=!:		
Signature Signat		Production Technician Date				
Mids the		September 23, 2005				
THIS SPACE FOR FEDERAL OR STATE USE					er ingleten som	
Approved by		Title		Date		
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		lease			Au	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						

(Instructions on reverse)

