

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Barrett A 1E	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004525943
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter G	Section 20	Township 31N	Range 09W	Feet from the 1640	North/South Line North	Feet from the 2215	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.88633 Longitude 107.80207

NATURE OF RELEASE

Type of Release: Condensate & Produced Water	Volume of Release: 50 bbls – condensate; 40 bbls – produced water	Volume Recovered: none
Source of Release: above ground production tank	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: 1 pm 1/30/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – NMOCD; Shari Ketcham – BLM	
By Whom? Courtney Cochran – BP	Date and Hour: 4:30 pm 1/30/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD FEB 5 '14
OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Sometime after 1/27/2014 the bull plug on the drain valve associated with the AGT froze and broke. The ball valve did not hold the contents of the tank due to corrosion. The majority of the contents of the AGT released to the unlined secondary containment area. Further investigation will need to take place to determine the depth of impacts. Excavation will be the means of remediation.

Describe Area Affected and Cleanup Action Taken.*

Currently a barricade was put in place to prevent access to the area. Further investigation will occur to determine extent of impacts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Field Environmental Advisor	Approval Date: 5/5/14	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/3/2014 Phone: 505-326-9457		

* Attach Additional Sheets If Necessary

#NCS 141252 6512