

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

X Initial Report Final Report

Name of Company: Enervest Operating LLC	Contact Lee Gardner
Address: 2700 Farmington Ave, Farmington NM 87041	Telephone No. 505-325-0318
Facility Name Jicarilla Apache Tribal 125-1	Facility Type Oil/Gas Production
Surface Owner Jicarilla Tribe	Mineral Owner BLM
API No. 30-039-20966	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	35	25N	4W	800	South	830	West	Rio Arriba

Latitude 36.356133 N Longitude 107.22076 W

NATURE OF RELEASE

Type of Release Unknown	Volume of Release Unknown	Volume Recovered 0
Source of Release Rupture flow line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 14:00 5-29-2014
Was Immediate Notice Given? <input type="checkbox"/> Yes X No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? X Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Unknown	

OIL CONS. DIV DIST. 3

If a Watercourse was Impacted, Describe Fully.*
Oil from the ruptured flow line flowed into a wash and traveled downstream approximately 1800 feet.

JUN 05 2014

Describe Cause of Problem and Remedial Action Taken.*
It appears that an exposed flow line rubbed on the rocks over time and developed a hole. The flow line was shut down and repaired

Describe Area Affected and Cleanup Action Taken.*
Enviro-Tech Inc has been contracted to develop a remediation plan. The remediation plan will be presented to the Jicarilla Apache Nation for approval. The Jicarilla Apache Nation would prefer a bio-remediation process to address the spill. Due to the inaccessibility of the location, the usage of mechanical equipment for clean-up activities is not possible. The location is accessible only by foot.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lee Gardner</i>	OIL CONSERVATION DIVISION	
Printed Name: Lee Gardner	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Sr. HSE Specialist	Approval Date: <i>6/12/14</i>	Expiration Date:
E-mail Address: wgardner@enervest.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6-4-2014	Phone: 505-325-0318	

* Attach Additional Sheets If Necessary

#NCS 141 6337003