

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Hart Oil & Gas, Inc.

3a. Address  
500 N. Cap. Tx Hwy Austin, Tx 78746

3b. Phone No. (include area code)  
512-637-6334

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
TWP 14 N R 6 E 10 N SEC 17 QTR SWSW

5. Lease Serial No.  
14-20-603-585

6. If Indian, Allottee or Tribe Name  
Navajo Tribal

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
Navajo TI AA #84

9. API Well No.  
30045207090051

10. Field and Pool, or Exploratory Area  
Many Rocks Gallup, North

11. County or Parish, State  
San Juan, N.M.

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

As per Notice of Intent, December 1, 2004, well was plugged and abandoned in and around September 15, 2005.



RECEIVED  
FARMINGTON NM  
OCT 12 AM 10 21

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Laura McClintock

Title Vice President

Signature Laura McClintock

Date 10-6-05

ACCEPTED FOR RECORD

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

OCT 18 2005

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office \_\_\_\_\_ BY Shm

NRMOCD

submitted in lieu of Form 3160-5

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**  
Sundry Notices and Reports on Wells

<b>1. Type of Well</b>  OIL	<b>5. Lease Number</b> BIA #14-20-603-585 <b>6. If Indian, All. or Tribe Name</b> Navajo <b>7. Unit Agreement Name</b>
<b>2. Name of Operator</b> Hart Oil and Gas, Inc.	<b>8. Well Name &amp; Number</b> Navajo AA #8Y
<b>3. Address &amp; Phone No. of Operator</b> 500 Capital Texas Highway, North, Austin, TX, 78746 (512) 637-6334	<b>9. API Well No.</b> 30-045-2070900S1
<b>4. Location of Well, Footage, Sec., T, R, M</b>  860' FSL and 830' FWL, Section 17, T-32-N, R-17-W,	<b>10. Field and Pool</b> Many Rocks Gallup, North <b>11. County &amp; State</b> San Juan County, NM

**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA**

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

**13. Describe Proposed or Completed Operations**

A-Plus Well Service Plugged and Abandoned this well on September 14, 2005 per the following:

9/6/05 MOL and RU rig. Well pressures: 0# tubing and casing. TOH and LD 67 - 5/8" rods, 2 - 4' subs and pump. Shut in well.

9/7/05 ND wellhead. NU BOP. TOH and LD 54 joints 2.375" tubing. TIH with 54 joints A+ 2.375" tubing. Tag bottom at 1678'. Load casing with 45 bbls of water and circulate casing clean. Plug #1 with 54 sxs Type III cement (71 cf) inside the casing from 1676' up to 900' to isolate the Gallup interval. TOH with tubing. Shut in well and WOC.

9/8/05 TIH and tag cement at 944'. Pressure test 4.5" casing to 500#, held OK. Perforate 3 holes at 80'. Establish circulation out the bradenhead with 8 bbls of water. Plug #2 with 30 sxs Type III cement (40 cf) inside the casing from 80' to surface, circulate good cement out bradenhead. ND BOP. Dig out around wellhead. Cut off wellhead. Found cement at the surface in the casing and down 15' in the annulus. Mix 15 sxs cement to fill the annulus and then install P&A marker. RD rig. Attempt to move rig. Radiator problems and muddy conditions. SDFD.

9/12/05 Roads washed out. Very muddy conditions. Need road work to be done to move out. SDFD.

9/13/05 MOL.  
Val Jameson, Navajo Nation Minerals, was on location.

SIGNATURE \_\_\_\_\_ Contractor \_\_\_\_\_ September 30, 2005  
William F. Clark

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

CONDITION OF APPROVAL, if any: