



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

November 10, 2005

Juanita Farrell  
Conocophillips Company  
5525 hwy 64  
Farmington, NM 87401

RE: San Juan 32-8 #12, M-21-31N-08W, API 30-045-10460

Dear Juanita:

**The 2005 Bradenhead test on the above well indicate a failure. Pressure on the intermediate casing is 105# and the 5 min build up is 105#. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to conduct remedial activity before February 13, 2005.**

**With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top. Provide gas analysis from both the production and intermediate casing.**

**Reference RBDMS CTP0531455347 on future correspondence.**

Notify the Aztec OCD 24 hours before work is initiated.

Thank you,

Charlie T. Perrin  
District Supervisor

CC: Well file  
CP